

REGULATOR INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8104160383 DOC. DATE: 81/04/07 NOTARIZED: NO DOCKET #
 FACIL: 50-220 Nine Mile Point Nuclear Station, Unit 1, Niagara Powe 05000220
 AUTH. NAME AUTHOR AFFILIATION
 LEMPGES, T.E. Niagara Mohawk Power Corp.
 RECIP. NAME RECIPIENT AFFILIATION
 Office of Management and Program Analysis

SUBJECT: Forwards monthly operating rept for Mar 1981.

DISTRIBUTION CODE: A0085 COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+4
 TITLE: Annual, Semi-Annual & Monthly Operating Reports (OL Stage)

NOTES:

ACTION:	RECIPIENT ID CODE/NAME	COPIES		RECIPIENT: ID CODE/NAME	COPIES	
		LTTR	ENCL		LTTR	ENCL
	IPPOLITO, T. 04	7	7			
INTERNAL:	D/DIR, HUM FAC07	1	1	I&E	06	2
	MPA 13	2	2	NRC PDR	02	1
	OP EX EVAL BR09	1	1	OR ASSESS BR	10	1
	RAD ASMT BR	1	1	<u>REG. FILE</u>	01	1
	T/A DSI	1	1			
EXTERNAL:	ACRS 11	1	1	BROOKHAVEN	12	1
	LPDR 03	1	1	NSIC	05	1

APR 17 1981

TOTAL NUMBER OF COPIES REQUIRED: LTTR 22 ENCL 22

KS



NINE MILE POINT NUCLEAR STATION / P.O. BOX 32 LYCOMING, NEW YORK 13093 / TELEPHONE (315) 343-2110

April 7, 1981

Director, Office of Management
Information and Program Control
United States Nuclear Regulatory Commission
Washington, D. C. 20555

RE: Docket No. 50-220
DPR-63



Gentlemen:

Submitted herewith is the Report of Operating Statistics and Shutdown Experience for March 1981 for the Nine Mile Point Nuclear Station Unit #1.

Also included is a Narrative Report of Operating Experience for the month of March 1981.

Very truly yours,

Thomas E. Lempges
Vice President
Nuclear Generation

jl/

Attachments

xc: Director, Office of I&E (10 copies) ✓

810.41.60 383

R

A008
6/11

NIAGARA MOHAWK POWER CORPORATION

NINE MILE POINT NUCLEAR STATION UNIT #1

NARRATIVE OF OPERATING EXPERIENCE

March 1981

The station operated with a monthly availability factor of 19.3% and a net design electrical capacity factor of 14.9%.

The unit was in operation March 1 through March 6 with a thermal power limit of 91.5% (end of cycle derate). During this time period #15 Reactor Recirculation Pump was out of service and isolated due to mechanical problems.

On March 7, the unit was removed from service for a scheduled refueling outage.

CLASS I WORK - MAINTENANCE - MARCH 1981

#11716 #11 F.W.P. internal inspection
3987 #15 R.R.P. internal replacement
#13270 &
#13271 #113 & 121 electromatic relief valve repairs
#13742 Repacked #11 F.W. Booster pump
M.O. 1651 - Containment Piping
M.O. 1849 - Emergency Vent to Torus
M.O. 1844 - Core Spray Pining
#13696 #13 FW flow control valves repair
Uncoupled 129 control rod drives
#18142 Inspected 200 moves for refueling grapple
#13371 Replaced refueling bridge grapple cable

CLASS I WORK - ELECTRICAL - MARCH 1981

Surveillance Test for 125V Battery
M.O. 1651 - Containment Piping
M.O. 1849 - Emergency Vent to Torus

CLASS I WORK - INSTRUMENT AND CONTROL - MARCH 1981

#13727 #12 Main Steam Line Warm Up Valve repaired copper tubing for operator
#13556 F.D.I.-N.B.T.S. replaced relay covers
#13664 A.B.R.M. #12 Intermittent Rod Blocks, found bent contact on Relay 7K10