

# REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8706080054 DOC. DATE: 87/05/29 NOTARIZED: NO DOCKET #  
 FACIL: 50-410 Nine Mile Point Nuclear Station, Unit 2, Niagara Moho 05000410  
 AUTH. NAME AUTHOR AFFILIATION  
 JOHNSTON, W. V. Region 1, Office of Director  
 RECIP. NAME RECIPIENT AFFILIATION  
 MANGAN, C. V. Niagara Mohawk Power Corp.

SUBJECT: Forwards Insp Rept 50-410/87-14 on 870413-17. Insp followed up on activities re installation of Rockwell Y pattern globe type MSIVs. No violations noted.

DISTRIBUTION CODE: IE01D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2+5  
 TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

## NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD1-1 LA	1 0	PD1-1 PD	1 1
	NEIGHBORS, D	2 2	MINER, S	2 2
INTERNAL:	ACRS	2 2	AEOD	1 1
	DEDRO	1 1	ENF LIEBERMAN	1 1
	NRR ROE, M. L.	1 1	NRR/DOEA DIR	1 1
	NRR/DREP/EPB	1 1	NRR/DREP/RPB	2 2
	NRR/DRIS DIR	1 1	NRR/PMAS/ILRB	1 1
	OGC/HDS1	1 1	<u>REG FILE</u>	1 1
	RES DEPY G1	1 1	RONI FILE 01	1 1
INTERNAL:	LPDR	1 1	NRC PDR	1 1
	NSIC	1 1		



MAY 29 1987

Docket No. 50-410

Niagara Mohawk Power Corporation  
ATTN: Mr. C. V. Mangan  
Senior Vice President  
301 Plainfield Road  
Syracuse, New York 13212

Gentlemen:

Subject: Inspection No. 50-410/87-14

This letter refers to the routine safety inspection conducted by Mr. H. Gregg of this office on April 13-17, 1987, at the Nine Mile Point Nuclear Station, Unit 2, Scriba, New York. Mr. Gregg discussed the findings of the inspection with Mr. M. Ray and other members of your staff at the conclusion of the onsite inspection.

The objective of this inspection was to follow-up on your activities related to installation of the new Rockwell "Y" pattern globe type Main Steam Isolation Valves (MSIVs). These new valves have replaced the Crosby ball type MSIVs. Areas examined during this inspection are described in the NRC Region I Inspection Report which is enclosed with this letter. Within these areas, the inspection consisted of selective examinations of records, interviews with personnel, and observations by the inspector.

Within the scope of this inspection, no violations were observed.

No reply to this letter is required. Your cooperation with us in this matter is appreciated.

Sincerely,

Original Signed By:  
Jacques P. Durr

William V. Johnston, Acting Director  
Division of Reactor Safety

Enclosure: NRC Region I Inspection Report No. 50-410/87-14

8706080054 870529  
PDR ADDCK 05000410  
Q PDR

OFFICIAL RECORD COPY

IR NMP2 87-14 - 0001.0.0  
05/22/87



cc w/encl:

Connor & Wetterhahn

John W. Keib, Esquire

J. A. Perry, Vice President, Quality Assurance

W. Hansen, Manager of Quality Assurance

D. Quamme, NMP-2 Project Director

C. Beckham, NMPC QA Manager

T. J. Perkins, General Superintendent

R. B. Abbott, Station Superintendent

Department of Public Service, State of New York

Public Document Room (PDR)

Local Public Document Room (LPDR)

Nuclear Safety Information Center (NSIC)

NRC Resident Inspector

State of New York

bcc w/encl:

Region I Docket Room (with concurrences)

Management Assistant, DRMA (w/o encl)

Region I SLO

Robert J. Bores, DRSS

J. Linville, DRP Section Chief #2C

J. Beall

L. Tripp

RI:DRS

Gregg

5/21/87

RI:DRS

Strosnider

5/26/87

RI:DRS

Durr

5/27/87

OFFICIAL RECORD COPY

IR NMP2 87-14 - 0001.0.1  
05/22/87

