REGUINTORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

"ACCESSION NBR: 8701150233 DDC. DATE: 87/01/12 NOTARIZED: YES DOCKET # FACIL: 50-410 Nine Mile Point Nuclear Station, Unit 2, Niagara Moha 05000410

AUTH. NAME

AUTHOR AFFILIATION

MANGAN, C. V.

Niagara Mohawk Power Corp.

RECIP. NAME RECIPIENT AFFILIATION

Record Services Branch (Document Control Desk)

SUBJECT: Discusses integrity of sys outside containment, per License

Condition 2. C(12). Summary of water testing results &

corrective maint encl, per Tech Spec 6.8.4. Leak test results

for RCIC included.

DISTRIBUTION CODE: A001D COPIES RECEIVED: LTR L ENCL SIZE: 5

NOTES:

	RECIPIENT ID CODE/NAME		COPIES LTTR ENCL		RECIPIENT ID CODE/NAME		COPIES LTTR ENCL	
	BWR EB		1	1	BWR EICSB		2	2
	BWR FOB		1	1	BWR PD3 LA		1	0
	BWR PD3 PD	01	5	5	HAUGHEY, M		1	1
	BUR PSB		1	1	BWR RSB		1	1
INTERNAL:	ACRS	09	6	6	ADM/LFMB		1	0
	ELD/HDS3		1	0	NRRADHETATSCI	3	1	1
	NRR/ORAS		1	0	REG FILE	04	1	1
EXTERNAL:	EG&G BRUSKE,	5	1	1	LPDR	03	1	1
•	NRC PDR	02	1	1	NSIC	05	1	1

AREA SE LE CONTRACTOR DESCRIPTION OF THE CONTRACTOR OF THE CONTRAC

Cultification beschiebliche Courtification of the Courtification o 4 (34.70) TACEL OF AD Name is not have increased in the same of the control of the same of the control of WINGS ON STATES Florida Rolls Value Will

grot regar or whole is people MITALL LA PROPERTIES

Caself for heart becomeson a someth some all because

ាក់ ព្រះសំខាន់ នាក់ សាក្សា សិក្សា និស្សាម្នាក់ ស្រុក ខណ្ឌព្រះ ប្រើក្រុង អ៊ី សង្គ្រាក់ ស្រុក ार्थी के बार के विकास के में किया है के अपने किया में बार के बार के मान के मान के मान के मान के किया है है है a shuffered board to b

WELLING CROWN AGOLD IN THIS RECEIVED THE ENGLY BY STREET THE the Green and Language Conference of the Conference

25, 15,

PTO THE SHOPE

		FIRE L		*	* K : [] " J "	ŧ	Mar I. Sain	
150/3	14 . E 3	1 84 10 at) al		71 1 X	3/4/0	Was it is	
<u> 5</u>	4 ,*	8 (D)	"1 331 Mg	ć ₉	l		据了 NE.N	
(3)	¥,	A + > C	19 5/3	i	<u>)</u>		1433 1441	
E	ì	'i . Y	il oldan	Ą	1	, t .	त्तु । १६३ । इस्तुहरू	
1	Į.	¥4.	THE FILE	=	· ·		901 div.	
F ^a r		> ≸;	LINE CO.	-1	Ò	4.3	25 JA	# \$f5.45\$ Path
7	Ŋ.	8')&\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	10× 45 N	2	*		子名代·普里古代 美艺	
1	E 1	94C - 37.E	* 35 4 3	ō	8		1. C 41377 x11 , 1. 1	
á	ģ.	524	5001	Ų	ŝ	, <u>*</u> ,	INDIPAG OF A	
Y	<u> </u>	' ₁ ;C,	2754	•	¥	m()	War . H	



NIAGARA MOHAWK POWER CORPORATION/301 PLAINFIELD ROAD, SYRACUSE, N.Y. 13212/TELEPHONE (315) 474-1511

January 12, 1987 (NMP2L 0969)

U.S. Nuclear Regulatory Commission Attn: Document Control Desk Washington, D.C. 20555

Re: Nine Mile Point Unit 2
Docket No. 50-410

Gentlemen:

This letter is in response to license condition described in paragraph 2.C(12), of our Facility Operating License No. NPF-54, concerning the integrity of systems outside the containment.

In our letter of December 2, 1985, we outlined a program for reducing the leakage of selected systems outside the containment to as low as practical limits. The program proposed a combination of testing using a helium tracer and visual inspection. It was found that for air or gas filled systems, the helium tracer provided the most accurate results. However, for the liquid filled systems, the leak detection by the visual method was more accurate.

In accordance with Technical Specification 6.8.4 and the above license commitment, the attached provides a summary of test results and any corrective maintenance required to date. The leak test results for the Reactor Core Isolation Cooling System (RCIC) were to be submitted at a later date. However, this testing is complete and the results are also included in this summary.

Very truly yours,

B701150233 870112 PDR ADBCK 05000410

C. V. Mangan Senior Vice President

TS/pns 2336G Attachments

xc: Mr. R. Vollmer, Regional Administrator, Region I
 Ms. E. G. Adensam, Project Director
 Mr. W. A. Cook, Resident Inspector
 Project File (2)

1001



UNITED STATES OF AMERICA NUCLEAR REGULATORY COMMISSION

In the Matter of Niagara Mohawk Power Corporation (Nine Mile Point Unit 2)]] Docket No. 50-410]
	AFFIDAVIT
part or said Corporation to sign a	ly sworn, states that he is Senior Vice Corporation; that he is authorized on the and file with the Nuclear Regulatory hereto; and that all such documents are true owledge, information and belief.
	- Emangan
Subscribed and even to before me	- Makawa Buk Maria and Garage and Garage
	, a Notary Public in and for the State of
of <u>January</u> , 1987.	laga, this 124 day
Sette A. Mexikiemi Notary Public in and for Omendaga County, New	York
My Commission expires: BETH A. MENIKHEIM Notary Public in the State of New York Qualified in Onendaga County No. 4804074 My Commission Expires August 31, 19.88	•.


AT A ME BY TO DO THE

-' a

ATTACHMENT

MATER TESTING

<u>SYSTEM</u>	PROCEDURE	DATE COMPLETED	<u>COMPONENT</u> <u>LEAKAGE</u>
Residual Heat Removal (RHS) 'A'	N2-OSP-RHS-Q004	9/30/86	2RHS*MOV2A Wet 2RHS*HCV119 1 Drop/Min. 2RHS*V265 1 Drop/Min. 2RHS*MOV8A 1 Drop/Min. 2RHS*MOV12A 1 Drop/Min. 2RHS*LV17A 1 Drop/Min. TOTAL 5 Drops/Min. NO CORRECTIVE ACTION REQUIRED
RHS 'B'	N2-OSP-RHS-Q005	10/3/86	2RHS*FE14B 3 Drops/Min. 2RHS*V348 1 Drop/5 Min. TOTAL 3.2 Drops/Min. NO CORRECTIVE ACTION REQUIRED
RHS 'C'	N2-OSP-RHS-Q006	9/26/86	TOTAL O NO CORRECTIVE ACTION REQUIRED
RHS (Shutdown Cooling)	N2-OSP-LIQ-ROO1	8/13/86	TOTAL O NO CORRECTIVE ACTION REQUIRED
RHS (STM Condensing Cond. Return)	N2-OSP-LIQ-R002	8/5/86	TOTAL O NO CORRECTIVE ACTION REQUIRED
Low Pressure Core Spray (CSL)	N2-OSP-CSL-Q002	9/26/86	TOTAL O NO CORRECTIVE ACTION REQUIRED
High Pressure Core Spray (CSH)	N2-OSP-CSH-Q002	9/19/86	2CSH*MOV111 1 Drop/Min. TOTAL 1 Drop/Min. NO CORRECTIVE ACTION REQUIRED



SYSTEM	PROCEDURE	DATE COMPLETED	COMPONENT	<u>LEAKAGE</u>
Post Accident Sampling (SSP)	N2-OSP-LIQ-R003	9/12/86	TOTAL 0	
			NO CORRECTIVE A	ACTION REQUIRED
Reactor Sampling System (SSR)	N2-OSP-LIQ-R004	7/18/86	TOTAL 0	
			NO CORRECTIVE A	ACTION REQUIRED
	······································			

HELIUM TESTING

SYSTEM	PROCEDURE	DATE COMPLETED	COMPONENT	LEAKAGE
RHS (STM Condensing)	N2-OSP-GAS-ROO1	10/28/86	2RHS*V198 2RHS*MOV9A	offscale '30 (medium deflection onscale)
		*	2RHS*SV62A	<pre>20 (low deflection onscale)</pre>
			2RHS*SOV71B	
			2RHS*MOV26A	30 (medium deflection onscale)
			2RHS*RV56A	40 (high deflection onscale)
			2RHS*V392	offscale
		•	2RHS*V97	offscale
			2RHS*MOV22A	·30 (medium
•				deflection onscale)
			2RHS*MOV80A	25 (low/medium
		•	ч	deflection onscale)
				-
RE	PLACED PACKING ON	2RHS*V198, V	392, V97 AND	RETESTED W/ZERO LEAKAGE
Standby Gas (GTS) and Containment	N2-OSP-GAS-ROO1	8/30/86	TOTAL (,

Purge (CPS)

NO CORRECTIVE ACTION REQUIRED

Reactor Core Isolation Cooling (ICS)

N2-OSP-GAS-ROO1

12/12/86

2ICS*MOV150

upscale

REPLACING FLEX HOSES IN SEAL LINE TO GOVERNING VALVE AND TRIP THROTTLE VALVE
- WORK IN PROGRESS

, . • . • 1

SYSTEM	PROCEDURE	COMPLETED	COMPONENT	<u>LEAKAGE</u>
Hydrogen Recombiner (HCS)	N2-OSP-GAS-ROO1	12/26/86	2HCS*V51 2HCS*V50	upscale upscale
	REPLACING	PACKING ON 2HO	CS*V50 AND V51 - W	ORK IN PROGRESS
Primary Containment Monitoring (CMS)	N2-OSP-GAS-ROO1	12/8/86	TOTAL 0	
			NO CORRECTIVE A	ACTION REOUIRED

2, 7 ι • . * 1 · 4,