## ACCELERATED DOCUMENT DISTRIBUTION SYSTEM (RIDS)

FACIL:50		nt Nuclear S FFILIATION ohawk Power T AFFILIATIO	Station, Unit 1, N. Corp.	iagara Powe	DOCKET # 05000220
SUBJECT: Special rept:on 930622,11 HMS unit taken out of svc to perform maint on containment oxygen analyzer. Analyzer cannot be repaired, parts no longer available. Instrument					I
-	must be replaced.	d,parts no 1			, D
DISTRIBUTION CODE: IE22D COPIES RECEIVED:LTR $\frac{1}{1}$ ENCL $\frac{6}{1}$ SIZE: $\frac{1}{1}$ TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.					s
NOTES:	•				/
	RECIPIENT	COPIES	RECIPIENT	COPIES	A
	ID CODE/NAME PD1-1 LA BRINKMAN, D.	LTTR ENCL	ID CODE/NAME PD1-1 PD	LTTR ENCL	D
INTERNAL:	·	2 2	ACRS	2 3	D
INIUMAN.	AEOD/DOA AEOD/ROAB/DSP NRR/DE/EMEB NRR/DRCH/HHFB NRR/DRCH/HOLB NRR/DRSS/PRPB NRR/DSSA/SRXB RES/DSIR/EIB	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	AEOD/DSP/TPAB NRR/DE/EELB NRR/DORS/OEAB NRR/DRCH/HICB NRR/DRIL/RPEB NRR/DSSA/SPLB REG FILE 02 RGN1 FILE 01	2 2 1 1 1 1 1 1 1 1 1 1	S
EXTERNAL:	EG&G BRYCE, J.H NRC PDR NSIC POORE, W.	2 2 1 1 1 1	L ST LOBBY WARD NSIC MURPHY,G.A	1 1	R
	NSIC POORE, W.	T 4	NUDOCS FULL TXT	1 1	I
					D
					S
					1
					Α
					D
,	NOTE TO ALL "RIDS" RECIPIE	PTG.			D
PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 504-2065) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!					





Kim A. Dahlberg Plant Manager

(315) 349-2443 (316) 349-2640 (FAX) July 6, 1993 NMP88380

United States Nuclear Regulatory Commission Attn: Document Control Desk Washington, DC 20555

RE:

Nine Mile Point Unit 1 Docket No. 50-220 DPR-63

Subject:

SPECIAL REPORT

Gentlemen:

In accordance with Nine Mile Point Unit 1 (NMP1) Technical Specification Table 3.6.11-1, "Accident Monitoring Instrumentation," Action Statement 4.a, Niagara Mohawk Power Corporation is submitting the following Special Report concerning the inoperability of the #11 Containment Hydrogen Monitoring Unit (HMS).

## **DESCRIPTION OF EVENT**

On June 22, 1993, at 0825 hours, with the reactor mode switch in the "RUN" position and the plant operating at approximately 100% rated thermal power, the #11 HMS unit was taken out of service to perform maintenance on its associated #11 containment oxygen analyzer. The #11 containment oxygen analyzer is not a Technical Specification required system. Routine preventive maintenance was also scheduled to be performed on #11 HMS.

## CAUSE OF EVENT

It is necessary to remove the #11 HMS from service to perform major maintenance on the #11 containment. oxygen analyzer because the two instruments share a common power supply and sample pump.

## CORRECTIVE ACTIONS

The #11 containment oxygen analyzer cannot be repaired because qualified parts are no longer available for this instrument. The #11 oxygen analyzer will remain out of service pending replacement. The #11 HMS will be returned to service after completion of its preventive maintenance.

· Very truly yours,

K. A. Dahlberg

Plant Manager, NMP1

Kc Jallber

KAD/JTP/Imc

xc:

Mr. Thomas T. Martin, Regional Administrator Region I

Mr. Wayne L. Schmidt, Senior Resident Inspector