

CATEGORY 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9703070108 DOC. DATE: 97/02/27 NOTARIZED: NO DOCKET #
 FACIL: 50-410 Nine Mile Point Nuclear Station, Unit 2, Niagara Moha 05000410
 AUTH. NAME AUTHOR AFFILIATION
 CONWAY, J.T. Niagara Mohawk Power Corp.
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Confirms 970227 telcon re delay in issuance of supplement 1 to LER 96-15 until 970328.

DISTRIBUTION CODE: IE22D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID CODE/NAME		LTR	ENCL		ID CODE/NAME		LTR	ENCL
	PDI-1 PD		1	1		HOOD, D		1	1
INTERNAL:	ACRS		1	1		AEOD/SPD/RAB		2	2
	AEOD/SPD/RRAB		1	1		FILE CENTER		1	1
	NRR/DE/ECGB		1	1		NRR/DE/EELB		1	1
	NRR/DE/EMEB		1	1		NRR/DRCH/HHFB		1	1
	NRR/DRCH/HICB		1	1		NRR/DRCH/HOLB		1	1
	NRR/DRCH/HQMB		1	1		NRR/DRPM/PECB		1	1
	NRR/DSSA/SPLB		1	1		NRR/DSSA/SRXB		1	1
	RES/DET/EIB		1	1		RGN1 FILE 01		1	1
EXTERNAL:	L ST LOBBY WARD		1	1		LITCO BRYCE, J H		1	1
	NOAC POORE, W.		1	1		NOAC QUEENER, DS		1	1
	NRC PDR		1	1		NUDOCS FULL TXT		1	1


NOTE TO ALL "RIDS" RECIPIENTS:
 PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM OWFN 5D-5 (EXT. 415-2083) TO ELIMINATE YOUR NAME FROM
 DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR 25 ENCL 0

C
A
T
E
G
O
R
Y

1

D
O
C
U
M
E
N
T





NIAGARA MOHAWK
GENERATION
BUSINESS GROUP

NINE MILE POINT NUCLEAR STATION/LAKE ROAD, P.O. BOX 63, LYCOMING, NEW YORK 13093

February 27, 1997
NMP2L 1691


U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555

RE: LER 96-15, Supplement 1
Docket No. 50-410

Gentlemen:

As discussed with NRC Resident Inspector Rick Skokowski on February 27, 1997, NMPC is delaying issuing Supplement 1 to the subject LER until March 28, 1997. On February 27, 1997, additional valves were identified as being potentially susceptible to mechanical damage from hot shorts. Therefore, additional time is required to complete the supplemental report.

Very truly yours,


John T. Conway
Plant Manager - NMP2

JTC/GJG/lmc
Enclosure

xc: Mr. H. J. Miller, Regional Administrator
Mr. B. S. Norris, Senior Resident Inspector
Records Management

TE22/0

9703070108 970227
PDR ADDCK 05000410
S PDR



