Mr. B. Ralph Sylvia Executive Vice Preside Generation Business Group and Chief Nuclear Officer Niagara Mohawk Power Corporation Nuclear Learning Center 450 Lake Road Oswego, NY 13126

SUBJECT: FLAW EVALUATION OF RECIRCULATION LINE WELD 32-WD-050 FOR NINE MILE POINT NUCLEAR STATION UNIT NO. 1 (TAC NO. M98414)

Dear Mr. Sylvia:

In a letter dated April 7, 1997, you provided the analytical evaluation of a rejectable weld indication in weld 32-WD-050. From your evaluation, you concluded that it is acceptable to operate Nine Mile Point Unit 1 (NMP1) for the upcoming cycle without repair of the weld indication. In a letter dated April 21, 1997, you informed us that you revised the NMP1 Inservice Inspection Program Plan to classify weld 32-WD-050 as a Category "F" weld. As a Category "F" weld, this weld will have to be examined during each refueling outage. The classification of weld 32-WD-050 did not change the conclusions reached in your April 7, 1997, letter.

Based on a review of your submittal and on independent crack growth calculations, the staff has concluded that NMP1 can be operated safely for the next cycle without repair to weld 32-WD-050, because the structural integrity of this weld will be maintained. The acceptability of operation beyond the next fuel cycle without repair to this weld will depend upon the results of the re-inspection during the next refueling outage that you committed to in your letter dated April 21, 1997.

The staff's safety evaluation is enclosed. If you have any questions, please call me at (301) 415-3049.

Sincerely,

ORIGINAL SIGNED BY:

Darl S. Hood, Senior Project Manager Project Directorate I-1 Division of Reactor Projects - I/II Office of Nuclear Reactor Regulation

Docket No. 50-220

Enclosure: Safety Evaluation

cc w/encl: See next page

DISTRIBUTION:

VDocket File	 !	s.	Bajwa
PUBLIC		s.	Little
PDI-1 R/F	020052	D.	Hood
S. Varga	020002	G.	Wunder

PDR

T. Harris (e-mail only TLH3) OGC ACRS C. Cowgill, Region I

DOCUMENT NAME: G:\NMP1\NM198414.LTR

To receive a copy of this document, indicate in the box: "C" = Copy without attachment/enclosure "E" = Copy with attachment/enclosure "N" = No copy

OFFICE	PM: PT 1	E	PM:PDI-1	LA:PDI-1	D:PDI-1	
NAME	GWGrder/rsl		DHood DST	SLittle	SBajwa 160 X	,
DATE	04/37/197		04/30 /97	04/30/97	04/30/97	

NRC FILE CENTER COP

1 30, 1997

•

ĩ

۰ ۲

·

.

•

· ·



UNITED STATES NUCLEAR REGULATORY COMMISSION

WASHINGTON, D.C. 20555-0001

April 30, 1997

Mr. B. Ralph Sylvia Executive Vice President Generation Business Group and Chief Nuclear Officer Niagara Mohawk Power Corporation Nuclear Learning Center 450 Lake Road Oswego, NY 13126

SUBJECT: FLAW EVALUATION OF RECIRCULATION LINE WELD 32-WD-050 FOR NINE MILE POINT NUCLEAR STATION UNIT NO. 1 (TAC NO. M98414)

Dear Mr. Sylvia:

In a letter dated April 7, 1997, you provided the analytical evaluation of a rejectable weld indication in weld 32-WD-050. From your evaluation, you concluded that it is acceptable to operate Nine Mile Point Unit 1 (NMP1) for the upcoming cycle without repair of the weld indication. In a letter dated April 21, 1997, you informed us that you revised the NMP1 Inservice Inspection Program Plan to classify weld 32-WD-050 as a Category "F" weld. As a Category "F" weld, this weld will have to be examined during each refueling outage. The classification of weld 32-WD-050 did not change the conclusions reached in your April 7, 1997, letter.

Based on a review of your submittal and on independent crack growth calculations, the staff has concluded that NMP1 can be operated safely for the next cycle without repair to weld 32-WD-050, because the structural integrity of this weld will be maintained. The acceptability of operation beyond the next fuel cycle without repair to this weld will depend upon the results of the re-inspection during the next refueling outage that you committed to in your letter dated April 21, 1997.

The staff's safety evaluation is enclosed. If you have any questions, please call me at (301) 415-3049.

Sincerely,

ARL HOOL

Darl S. Hood, Senior Project Manager Project Directorate I-1 Division of Reactor Projects - I/II Office of Nuclear Reactor Regulation

Docket No. 50-220

Enclosure: Safety Evaluation

cc w/encl: See next page

4 • * •

·

•

B. Ralph Sylvia Niagara Mohawk Power Corporation

cc:

Mr. Richard B. Abbott Vice President and General Manager -Nuclear Niagara Mohawk Power Corporation Nine Mile Point Nuclear Station P.O. Box 63 Lycoming, NY 13093

Mr. Martin J. McCormick, Jr. Vice President Nuclear Safety Assessment and Support Niagara Mohawk Power Corporation Nine Mile Point Nuclear Station P.O. Box 63 Lycoming, NY 13093

Ms. Denise J. Wolniak Manager Licensing Niagara Mohawk Power Corporation Nine Mile Point Nuclear Station P.O. Box 63 Lycoming, NY 13093

Mr. Kim A. Dahlberg General Manager - Projects Niagara Mohawk Power Corporation Nine Mile Point Nuclear Station P.O. Box 63 Lycoming, NY 13093

Mr. Norman L. Rademacher Plant Manager, Unit 1 Nine Mile Point Nuclear Station P.O. Box 63 Lycoming, NY 13093

Regional Administrator, Region I U.S. Nuclear Regulatory Commission 475 Allendale Road King of Prussia, PA 19406

Resident Inspector U.S. Nuclear Regulatory Commission P.O. Box 126 Lycoming, NY 13093 Nine Mile Point Nuclear Station Unit No. 1

Charles Donaldson, Esquire Assistant Attorney General New York Department of Law 120 Broadway New York, NY 10271

Mr. Paul D. Eddy State of New York Department of Public Service Power Division, System Operations 3 Empire State Plaza Albany, NY 12223

Mr. F. William Valentino, President New York State Energy, Research, and Development Authority Corporate Plaza West 286 Washington Avenue Extension Albany, NY 12203-6399

Mark J. Wetterhahn, Esquire Winston & Strawn 1400 L Street, NW Washington, DC 20005-3502

Gary D. Wilson, Esquire Niagara Mohawk Power Corporation 300 Erie Boulevard West Syracuse, NY 13202

Supervisor Town of Scriba Route 8, Box 382 Oswego, NY 13126 •

•

L

____. ·