

# CATEGORY 1

## REGULATOR INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9707160169      DOC. DATE: 97/07/07      NOTARIZED: NO      DOCKET #  
 FACIL: 50-410 Nine Mile Point Nuclear Station, Unit 2, Niagara Moha      05000410  
 AUTH. NAME:      AUTHOR AFFILIATION  
 DAHLBERG, K.A.      Niagara Mohawk Power Corp.  
 RECIP. NAME      RECIPIENT AFFILIATION  
                                  Document Control Branch (Document Control Desk)

SUBJECT: Forwards LER 97-002-02 re potential inoperability of EDG SW cooling outlet valves during CR fire.

DISTRIBUTION CODE: IE22T      COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+8  
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

### NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD1-1 PD	1 1	HOOD, D	1 1
INTERNAL:	ACRS	1 1	<del>AEOD/SPD/RAB</del>	2 2
	AEOD/SPD/RRAB	1 1	<b>FILE CENTER</b>	1 1
	NRR/DE/ECGB	1 1	NRR/DE/EELB	1 1
	NRR/DE/EMEB	1 1	NRR/DRCH/HHFB	1 1
	NRR/DRCH/HICB	1 1	NRR/DRCH/HOLB	1 1
	NRR/DRCH/HQMB	1 1	NRR/DRPM/PECB	1 1
	NRR/DSSA/SPLB	1 1	NRR/DSSA/SRXB	1 1
	RES/DET/EIB	1 1	RGN1 FILE 01	1 1
EXTERNAL:	L ST LOBBY WARD	1 1	LITCO BRYCE, J H	1 1
	NOAC POORE, W.	1 1	NOAC QUEENER, DS	1 1
	NRC PDR	1 1	NUDOCS FULL TXT	1 1

C  
A  
T  
E  
G  
O  
R  
Y  
  
1  
  
D  
O  
C  
U  
M  
E  
N  
T

NOTE TO ALL "RIDS" RECIPIENTS:  
 PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,  
 ROOM OWFN 5D-5 (EXT. 415-2083) TO ELIMINATE YOUR NAME FROM  
 DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED  
 TOTAL NUMBER OF COPIES REQUIRED: LTR 25 ENCL 25

AD4





NIAGARA MOHAWK

GENERATION  
BUSINESS GROUP

NINE MILE POINT NUCLEAR STATION/LAKE ROAD, P.O. BOX 63, LYCOMING, NEW YORK 13093

July 7, 1997  
NMP2L 1714

U. S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, DC 20555

RE: Docket No. 50-410  
LER 97-02  
Supplement 2

Gentlemen:

In accordance with 10CFR50.73 (a)(2)(i)(B) and 10CFR50.73 (a)(2)(ii)(B), we are submitting LER 97-02, Supplement 2 "Potential Inoperability of Emergency Diesel Generator Service Water Cooling Outlet Valves During a Control Room Fire." This supplement is submitted based upon a deficiency identified during corrective actions being taken for the initial event. In addition, the commitment date for installing eight hour capacity battery lights has been revised as discussed with Mr. B. S. Norris.

Very truly yours,

*Kim A. Dahlberg*  
Kim A. Dahlberg  
Plant Manager - NMP2

*11/1 DE 22*

KAD/GJG/lmc  
Attachment

xc: Mr. H. J. Miller, Regional Administrator, Region I  
Mr. B. S. Norris, Senior Resident Inspector  
Records Management

9707160169 970707  
PDR ADDCK 05000410  
S PDR



100011

