Mr. John H. Mueller Chief Nuclear Officer Niagara Mohawk Power Corporation Nine Mile Point Nuclear Station Operations Building, Second Floor P.O. Box 63 Lycoming, NY 13093

SUBJECT: REQUEST FOR ADDITIONAL INFORMATION REGARDING CORE SHROUD

EVALUATION FROM REFUELING OUTAGE 6 (RFO6) - NINE MILE POINT

NUCLEAR STATION UNIT NO. 2 (TAC NO. MA2286)

Dear Mr. Mueller:

By letter dated July 9, 1998, you submitted results of the inspections of the core shroud during RFO6 at Nine Mile Point Nuclear Station Unit 2 (NMP2). You also provided the evaluation that was performed to support continued operation of NMP2. The NRC staff is reviewing your submittal and finds that the following additional information is needed:

For the compound flaw at horizontal weld H4, you apply a stress intensity factor formula, Equation (4-1), which is applicable for R/t values ranging from 5 to 10. Please provide details supporting your following statement: "The R/t value for the shroud geometry is approximately 50. However, a review of available analytical solutions for through-wall and part-through-wall circumferential cracks showed that the stress intensity factor predictions of Equation (4-1) are conservative. Therefore, the use of Equation (4-1) for this evaluation was justified."

Your response to this letter is requested within 45 days of its receipt. If you should have any questions regarding this request or are unable to meet the requested response schedule, please contact me by phone on (301) 415-3049 or by electronic mail at dsh@nrc.gov.

Sincerely,

Original Signed by: Darl S. Hood, Senior Project Manager Project Directorate I-1 Division of Reactor Projects - I/II Office of Nuclear Reactor Regulation

Docket No. 50-220

cc: See next page

DISTRIBUTION:

PDI-1 R/F

Docket File **SBajwa** PUBLIC

JZwolinski (A) CSheng

SLittle DHood OGC ACRS RHermann

KWichman CCarpenter


LDoerflein, RI **ESullivan**

DOCUMENT NAME: G:\NMP1\NM2A2286.RAI

To receive a copy of this document, indicate in the box: "C" = Copy without attachment/enclosure "E" = Copy with attachment/enclosure "N" = No conv

OFFICE	PM:PDI-1 E	LA:PDI-1 n()	D:PDI-1	встеняв 🗸	Now	
NAME	DHood/rst 5.(/+	SLittle	SBajwa /80	ESULTIVERY	V	
DATE	08/20/98	08/ <i>QC</i> /98	08/24/98	08/20198		

9808270095 980824 PDR ADDCK 05000220 Official Record Copy



August 24, 1998

Mr. John H. Mueller
Chief Nuclear Officer
Niagara Mohawk Power Corporation
Nine Mile Point Nuclear Station
Operations Building, Second Floor
P.O. Box 63
Lycoming, NY 13093

SUBJECT: REQUEST FOR ADDITIONAL INFORMATION REGARDING CORE SHROUD

EVALUATION FROM REFUELING OUTAGE 6 (RFO6) - NINE MILE POINT

NUCLEAR STATION UNIT NO. 2 (TAC NO. MA2286)

Dear Mr. Mueller:

By letter dated July 9, 1998, you submitted results of the inspections of the core shroud during RFO6 at Nine Mile Point Nuclear Station Unit 2 (NMP2). You also provided the evaluation that was performed to support continued operation of NMP2. The NRC staff is reviewing your submittal and finds that the following additional information is needed:

For the compound flaw at horizontal weld H4, you apply a stress intensity factor formula, Equation (4-1), which is applicable for R/t values ranging from 5 to 10. Please provide details supporting your following statement: "The R/t value for the shroud geometry is approximately 50. However, a review of available analytical solutions for through-wall and part-through-wall circumferential cracks showed that the stress intensity factor predictions of Equation (4-1) are conservative. Therefore, the use of Equation (4-1) for this evaluation was justified."

Your response to this letter is requested within 45 days of its receipt. If you should have any questions regarding this request or are unable to meet the requested response schedule, please contact me by phone on (301) 415-3049 or by electronic mail at dsh@nrc.gov.

Sincerely,

Original Signed by:
Darl S. Hood, Senior Project Manager
Project Directorate I-1
Division of Reactor Projects - I/II
Office of Nuclear Reactor Regulation

Docket No. 50-220

cc: See next page

DISTRIBUTION:

PDI-1 R/F

Docket File SBajwa PUBLIC SLittle

OGC ACRS RHermann KWichman

LDoerflein, RI

CCarpenter

JZwolinski (A) CSheng

ESullivan

DOCUMENT NAME: G:\NMP1\NM2A2286.RAI

DHood

To receive a copy of this document, indicate in the box: "C" = Copy without attachment/enclosure "E" = Copy with

attachment/enclosure "N" = No copy

OFFICE	PM:PDI-1	E LA:PDI-1 ()	D:PDI-1 AND	BCZEMAB (1/0/)	
NAME	DHood/rsl b.(//	SLittle	SBajwa 100-	Equilivan b	
DATE	08/20/98	08/ <i>QC</i> /98	08/24 198	08/20/98	

		,		,	
	, p				
		•			,
			,		
•		· .			
		•			
	,	•		•	



UNITED STATES NUCLEAR REGULATORY COMMISSION

WASHINGTON, D.C. 20555-0001

August 24, 1998

Mr. John H. Mueller Chief Nuclear Officer Niagara Mohawk Power Corporation Nine Mile Point Nuclear Station Operations Building, Second Floor P.O. Box 63 Lycoming, NY 13093

SUBJECT: REQUEST FOR ADDITIONAL INFORMATION REGARDING CORE SHROUD

EVALUATION FROM REFUELING OUTAGE 6 (RFO6) - NINE MILE POINT

NUCLEAR STATION UNIT NO. 2 (TAC NO. MA2286)

Dear Mr. Mueller:

By letter dated July 9, 1998, you submitted results of the inspections of the core shroud during RFO6 at Nine Mile Point Nuclear Station Unit 2 (NMP2). You also provided the evaluation that was performed to support continued operation of NMP2. The NRC staff is reviewing your submittal and finds that the following additional information is needed:

For the compound flaw at horizontal weld H4, you apply a stress intensity factor formula, Equation (4-1), which is applicable for R/t values ranging from 5 to 10. Please provide details supporting your following statement: "The R/t value for the shroud geometry is approximately 50. However, a review of available analytical solutions for through-wall and part-through-wall circumferential cracks showed that the stress intensity factor predictions of Equation (4-1) are conservative. Therefore, the use of Equation (4-1) for this evaluation was justified."

Your response to this letter is requested within 45 days of its receipt. If you should have any questions regarding this request or are unable to meet the requested response schedule, please contact me by phone on (301) 415-3049 or by electronic mail at dsh@nrc.gov.

Sincerely.

Darl S. Hood, Senior Project Manager


Project Directorate I-1

Darl & Hord

Division of Reactor Projects - I/II
Office of Nuclear Reactor Regulation

Docket No. 50-220

cc: See next page



John H. Mueller Niagara Mohawk Power Corporation

CC:

Regional Administrator, Region I U. S. Nuclear Regulatory Commission 475 Allendale Road King of Prussia, PA 19406

Resident Inspector Nine Mile Point Nuclear Station P.O. Box 126 Lycoming, NY 13093

Mr. Jim Rettberg NY State Electric & Gas Corporation Corporate Drive Kirkwood Industrial Park P.O. Box 5224 Binghamton, NY 13902-5224

Mr. John V. Vinquist, MATS Inc. P.O. Box 63 Lycoming, NY 13093

Supervisor Town of Scriba Route 8, Box 382 Oswego, NY 13126

Mr. Richard Goldsmith
Syracuse University
College of Law
E.I. White Hall Campus
Syracuse, NY 12223

Nine Mile Point Nuclear Station Unit No. 2

Charles Donaldson, Esquire Assistant Attorney General New York Department of Law 120 Broadway New York, NY 10271

Mr. Timothy S. Carey Chair and Executive Director State Consumer Protection Board 5 Empire State Plaza, Suite 2101 Albany, NY 12223

Mark J. Wetterhahn, Esquire Winston & Strawn 1400 L Street, NW. Washington, DC 20005-3502

Gary D. Wilson, Esquire Niagara Mohawk Power Corporation 300 Erie Boulevard West Syracuse, NY 13202

Mr. F. William Valentino, President New York State Energy, Research, and Development Authority Corporate Plaza West 286 Washington Avenue Extension Albany, NY 12203-6399

J., N. , • • u E