

THE CHURCH OF
JESUS CHRIST
OF LATTER-DAY SAINTS

RIGBY ID FM GROUP
10663 North 34 East
P.O. Box 26
Ucon, Idaho 83454-0026
Phone: 1-208-523-6554
Facsimile: 1-208-523-2545

2/14/2017

Director of FSME
Attn: GLTS
USNRC
Washington, DC 20555-0001

In fulfillment of the requirements of 10 CFR 31.5 (c) 8, we hereby notify you that on 2/10/2017 we transferred the self-luminous exit signs listed on the attached spreadsheet to SRBT, 320 Boundary Rd., Suite 140, Pembroke, Ontario, K8A 6W5, Canada with CNSC License #NSPFOL-13.00/2022. As required, for each sign listed on the spreadsheet, we include the name of the manufacturer, model number, and serial number.

If you should have any questions, please contact Orlin Clements at 208-681-6554.

Sincerely,



Orlin Clements; Rigby Facility Manager

Encl.

[Faint, illegible text, likely bleed-through from the reverse side of the page]



**Return Merchandise
Authorization**

PO # FMACQ-208480

Expiration Date: 2/28/2017

RMA Date:	1/30/2017
Orig. Invoice Date:	1/27/2017
RMA #	12669PA-RMA
Order #	96460PA
Terms	

Bill To: Corp of Presiding Bishop, CPB LDSInvoice@ldschurch.org Salt Lake City, UT 84103-1511 USA	Ship To: Rigby ID FM Group 10663 North 34 East Ucon, ID 83454 USA 208-523-6554 Dana Bell
--	---

PRODUCT NO	DESCRIPTION	QTY	PRICE	RESTOCK	EXTENDED PRICE
RETURN	Return of Expired Tritium Exits	25	\$0.00	0.00%	\$0.00

Subtotal: \$0.00
Restocking Fee: \$0.00
Total Credit: \$0.00

REP: * Christen Martin

Comments:

*** RMA# must appear on shipping label or return may be refused! ***
 *** If applicable a CREDIT will be issued upon receipt and inspection! ***

Return To:
ISOLITE RETURNS
 SRB Technologies (Canada), Inc
 320 Boundary Rd, Ste 140
 Pembroke, ON K8A 6W5
 CANADA
 Attn: RMA # 12669PA-RMA

SERIAL NUMBER SPREADSHEET

Company Name	Rigby FM Group	Date	6 Jan 2017
Address 1	10854 N 41 E	Isolite RMA #	
Address 2		EWS Order #	
Address 3		MTS Order #s	FMACB-208480
City/State	Ucon, ID	Contact Name	Dana Bell
Zip/Post Code	83454	Contact Phone	208-523-6554
Country	USA	Contact FAX	
		Contact E-mail	dana.bell@ldschurch.org

	Manufacturer Name	Model No.	Serial No.	Manufacture Date		Activity Include "Ci" or "TBq"
				Month	Year	
1	SRB Technologies	B100	608392	8	96	20 Ci
2	"	"	608408	"	"	"
3	"	"	608390	"	"	"
4	"	"	608405	"	"	"
5	"	"	608397	"	"	"
6	"	"	608411	"	"	"
7	"	"	608406	"	"	"
8	"	"	608398	"	"	"
9	"	"	608407	"	"	"
10	"	"	608394	"	"	"
11	"	"	608399	"	"	"
12	"	"	608401	"	"	"
13	"	"	608409	"	"	"
14	"	"	608404	"	"	"
15	"	"	608415	"	"	"

**The above information should be on the signs labels. If any information on the sign is missing please fill in the fields with "missing" or "illegible", etc. Please print clearly. A double sign is counted as "TWO" signs—not "ONE" Please make note of this.*

Once we have received and processed this information an RMA number will be issued.

If you have more signs that this form holds, please copy additional pages and filling all necessary information.

SERIAL NUMBER SPREADSHEET

Company Name	Rigby FM Group	Date	6 Jan 2017
Address 1	10854 N 41 E	Isolite RMA #	
Address 2		EWS Order #	
Address 3		MTS Order #s	
City/State	Ucon, ID	Contact Name	
Zip/Post Code	83454	Contact Phone	
Country	USA	Contact FAX	
		Contact E-mail	

	Manufacturer Name	Model No.	Serial No.	Manufacture Date		Activity Include "Ci" or "TBq"
				Month	Year	
1	SRB Technologies	B100	608402	8	96	20ci
2	"	"	608391	"	"	"
3	"	"	608403	"	"	"
4	"	"	608395	"	"	"
5	"	"	608393	"	"	"
6	"	"	608400	"	"	"
7	"	"	608410	"	"	"
8	"	"	608396	"	"	"
9	"	"	608417	"	"	"
10	"	"	608416	"	"	"
11						
12						
13						
14						
15						

25

**The above information should be on the signs labels. If any information on the sign is missing please fill in the fields with "missing" or "illegible", etc. Please print clearly. A double sign is counted as "TWO" signs—not "ONE" Please make note of this.*

Once we have received and processed this information an RMA number will be issued.

If you have more signs that this form holds, please copy additional pages and filling all necessary information.