



DIAMOND TECHNICAL SERVICES, INC.

Br. 2

3/09/17

REC RG 1 03 21 17 AM 06 57

To: Licensing Assistance Team

Re: License # 37-31259-01 / 03037501

To Whom It May Concern:

Please see the enclosed 2 documents. The first is a 180 day notification under 10 CFR 34.101(c). The second is a request for an amendment to the current license. Please contact me directly for any questions or if additional information is required.

Sincerely,

Gregory S. Prebish  
GM / Corporate RSO  
Quality / NDE Services  
724-668-5070

594358

9152 Route 22 Blairsville, PA 15717

Phone: (724) 668-5069 Fax: (724) 668-5071

NMSS/RGNI MATERIALS-002



DIAMOND TECHNICAL SERVICES, INC.

3-2-17

To: USNRC  
Region I  
Licensing Assistance Team

Re: 180 Day Notification

03037501

In accordance with the requirements of 10 CFR 34.101(c), Diamond Technical Services (License # 37-31259-01) is providing the following notification of use at a temporary jobsite that may exceed 180 days in the calendar year of 2017.

For the calendar of 2017, Diamond Technical Services (Monroe, MI office location) will be performing radiographic operations at Hemlock Semiconductor Corporation located at 12334 Geddes Road Hemlock, MI 48626 and expects to exceed the 180 day requirement during a calendar year.

If you have any questions or require any additional information, please contact me via the methods below

Gregory S. Prebish

C- RSO  
Diamond Technical Services  
724-668-5070 - Office  
gprebish@diamondtechnicalservices.com

REC'D IN LAT 03/02/2017

9152 Route 22 Blairsville, PA 15717

Phone: (724) 668-5069 Fax: (724) 668-5071



**ACKNOWLEDGEMENT - RECEIPT OF CORRESPONDENCE**

Name and Address of Applicant and/or Licensee  Diamond Technical Services, Inc. ATTN: Ralph H. Hill, Jr., Chief Operating Officer 9152 Route 22 Blairsville, PA 15717	Date
	March 27, 2017
	License Number(s)
	37-31259-01
	Mail Control Number(s)
594358	
Licensing and/or Technical Reviewer or Branch	
Commercial, Industrial, R&D, & Academic Branch (Branch 2) Notification	

This is to acknowledge receipt of your:  Letter and/or  Application Dated: 03/02/2017

The initial processing, which included an administrative review, has been performed.  
 Amendment  Termination  New License  Renewal

There were no administrative omissions identified during our initial review.

This is to acknowledge receipt of your application for renewal of the material(s) license identified above. Your application is deemed timely filed, and accordingly, the license will not expire until final action has been taken by this office.

Your application for a new NRC license did not include your taxpayer identification number. Please complete and submit NRC Form 531, Request for Taxpayer Identification Number, located at the following link: <http://www.nrc.gov/reading-rm/doc-collections/forms/nrc531.pdf>  
 Follow the instructions on the form for submission.

The following administrative omissions have been identified:

Your application has been assigned the above listed MAIL CONTROL NUMBER. When calling to inquire about this action, please refer to this control number. Your application has been forwarded to a technical reviewer. Please note that the technical review, which is normally completed within 180 days for a renewal application (90 days for all other requests), may identify additional omissions or require additional information. If you have any questions concerning the processing of your application, our contact information is listed below:

**Region I**  
**U. S. Nuclear Regulatory Commission**  
**Division of Nuclear Materials Safety**  
**2100 Renaissance Boulevard, Suite 100**  
**King of Prussia, PA 19406-2713**  
**(610) 337-5260, (610) 337-5313,**  
**(610) 337-5398, or (610) 337-5239**