



KHNP

KOREA HYDRO & NUCLEAR POWER CO., LTD

70-1312-gil, Yuseong-daero, Yuseong-gu, Daejeon, 305-343, KOREA

Tel: +82-42-870-5400 / Fax: +82-42-870-5449

<http://www.khnp.co.kr>

March 28, 2017
Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001

Attention: Mr. Jeff Ciocco
Division of New Reactor Licensing

Docket No. 52-046
MKD/NW-17-0081L

Subject: Revised Response to RAI 334-8373 for Question 03.12-10 (Rev. 3)

- References:**
- 1) NRC Request for Additional Information 334-8373, dated December 14, 2015
 - 2) KHNP Letter MKD/NW-16-0139L, Response to RAI 334-8373, dated February 19, 2016
 - 3) KHNP Letter MKD/NW-16-0916L, Revised Response to RAI 334-8373 for the Question 03.12-10, dated August 23, 2016
 - 4) KHNP Letter MKD/NW-16-1159L, Revised Response to RAI 334-8373 for Question 03.12-10 (Rev. 2), dated December 13, 2016

KHNP is hereby submitting a revised response to RAI 334-8373, dated February 19, 2016. The revised response addresses Question 03.12-10 to address the verification of gaps and clearances in supports during the reactor coolant system hot functional test. The enclosure contains the revised response to RAI 334-8373 for Question 03.12-10 (Rev. 3) (Non-Proprietary).

If additional information or clarification is required, please contact Daegeun Ahn, Director of KHNP Washington DC Center at ahn.daegeun@khnp.co.kr or 703-388-0592.

Sincerely,

Han-gon Kim
Project Manager
Advanced Reactors Development Laboratory
Korea Hydro & Nuclear Power Co., Ltd.

Enclosure: Revised Response to RAI 334-8373 for Question 03.12-10 (Rev. 3) (Non-Proprietary)

Enclosure

Revised Response to RAI 334-8373 for Question 03.12-10 (Rev. 3)

(Non-Proprietary)

March 28, 2017