


Stanton Cardiology Center

H. James Stanton, M.D.
F.A.C.C., F.S.C.A.I., F.A.S.E., F.A.S.N.C.
Board Certified in Cardiology
Board Certified in Interventional Cardiology
Board Certified in Nuclear Cardiology
Board Certified in Echocardiography
Board Certified in Internal Medicine
Stephen L. DiBlasi, D.O., F.A.C.O.I.
Nancy Elwood, M.D.

4315 MacCorkle Avenue SE
Charleston, WV 25304
304-926-8080 Office
304-926-8083 Fax



Br. 1

April 26, 2017

Licensing Assistance Team
Division of Nuclear Materials Safety
US Nuclear Regulatory Commission, Region I
2100 Renaissance Boulevard
King of Prussia, PA 19406-1415

License Number: ~~47-25572-021~~

RLJ

47-25572-01 03035785

REC RG 105 02 17 AM 06:57


To Whom It May Concern:

Please amend our radioactive materials license as follows:

Please remove Steven A. Artz, M.D. as an authorized user from our license as he is no longer providing services to our facility.

If you have any questions, please contact C. Kelly Stoneberg, 888-456-5255
Thank you for your attention to this matter.

Sincerely,


H. James Stanton, M.D.
Administration

594662
NMSC/RGN MATERIALS-02



ACKNOWLEDGEMENT - RECEIPT OF CORRESPONDENCE

Name and Address of Applicant and/or Licensee H. James Stanton, M.D. Administration Stanton, H. James M.D. 4315 MacCorkle Avenue, SE Charleston, WV 25304-2503	Date May 4, 2017
	License Number(s) 47-25572-01
	Mail Control Number(s) 594662
	Licensing and/or Technical Reviewer or Branch Medical Branch

This is to acknowledge receipt of your: Letter and/or Application Dated: April 26, 2017

The initial processing, which included an administrative review, has been performed.
 Amendment Termination New License Renewal

There were no administrative omissions identified during our initial review.

This is to acknowledge receipt of your application for renewal of the material(s) license identified above. Your application is deemed timely filed, and accordingly, the license will not expire until final action has been taken by this office.

Your application for a new NRC license did not include your taxpayer identification number. Please complete and submit NRC Form 531, Request for Taxpayer Identification Number, located at the following link: <http://www.nrc.gov/reading-rm/doc-collections/forms/nrc531.pdf>
 Follow the instructions on the form for submission.

The following administrative omissions have been identified:
 [Empty box for listing omissions]

Your application has been assigned the above listed MAIL CONTROL NUMBER. When calling to inquire about this action, please refer to this control number. Your application has been forwarded to a technical reviewer. Please note that the technical review, which is normally completed within 180 days for a renewal application (90 days for all other requests), may identify additional omissions or require additional information. If you have any questions concerning the processing of your application, our contact information is listed below:

Region I
U. S. Nuclear Regulatory Commission
Division of Nuclear Materials Safety
2100 Renaissance Boulevard, Suite 100
King of Prussia, PA 19406-2713
(610) 337-5260, (610) 337-5313,
(610) 337-5398, (610) 337-5239