



L-2017-082
May 5, 2017

Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001

Re: Turkey Point Units 3 and 4
Docket Nos. 50-250 and 50-251
Reply to Inspection Report 05000250/2014404 and 05000251/2014404

The referenced Inspection Report (IR) discusses four licensee identified violations of very low safety significance at the Turkey Point Plant. As discussed in the IR, the Nuclear Regulatory Commission (NRC) has exercised enforcement discretion for these licensee identified violations in accordance with the Security Issues Forum (SIF) Charter. Further, Florida Power & Light Company (FPL) was requested to notify the NRC of the method and date of closure for the identified issues. The attachment to this letter provides the FPL notification.

The attachment to this letter contains sensitive security-related information; therefore, FPL requests that it be withheld from public disclosure pursuant to 10 CFR 2.390.

This letter makes no new commitments nor changes to existing commitments.

If you have any questions related to this letter, please contact Mr. Mitch Guth, Licensing Manager at (305) 246-6698.

Sincerely,

A handwritten signature in black ink, appearing to read 'Thomas Summers', is written over a horizontal line.

Thomas Summers
Regional Vice President – Southern Region
Turkey Point Nuclear Plant

Attachment: Closure of Actions to Address Licensee Identified Violations

cc: USNRC Regional Administrator, Region II
USNRC Senior Resident Inspector, Turkey Point Nuclear Plant

The attachment to this letter contains Security-Related Information. Withhold from public disclosure in accordance with 10 CFR 2.390. Upon removal of the attachment, this letter is decontrolled.