

THE CHURCH OF
JESUS CHRIST
OF LATTER-DAY SAINTS

ST ANTHONY ID FM GROUP
631 North 2nd East, Suite 2
Rexburg, Idaho 83440-3599


April 3, 2017

Director of FSME
Attn: GLTS
USNRC
Washington, DC 20555-0001

In fulfillment of the requirements of 10 CFR 31.5 (c) 8, we hereby notify you that on April 3, 2017 we transferred the self-luminous exit signs listed on the attached spreadsheet to SRBT, 320 Boundary Rd., Suite 140, Pembroke, Ontario, K8A 6W5, Canada with CNSC License #NSPFOL-13.00/2022. As required, for each sign listed on the spreadsheet, we include the name of the manufacturer, model number, and serial number.

If you should have any questions, please contact Margo Thompson, 208-356-7184

Sincerely,



Margo Thompson
St. Anthony ID FM
Administrative Assistant

Encl.

SERIAL NUMBER SPREADSHEET

Company Name	St. Anthony TD FM	Date	3/27/17
Address 1	387 S. 4th E	Isolite RMA #	
Address 2		EWS Order #	FMAcO-204679
Address 3		MTS Order #s	FMAcO-204678
City/State	Rexburg ID	Contact Name	Margo Thompson
Zip/Post Code	83440	Contact Phone	208-356-7184
Country	USA	Contact FAX	
		Contact E-mail	thompsonmve@dschuck.org

	Manufacturer Name	Model No.	Serial No.	Manufacture Date		Activity Include "CI" or "TBq"	
				Month	Year		
1	SRB	B100	606802	5	97	20 ci	Box 1
2	SRB	B100	606799	5	97	20 ci	
3	SRB	B100	606801	5	97	20 ci	
4	SRB	B100	602110	illegible	illegible	20 ci	
5	SRB	B100	602116	"	"	20 ci	Box 2
6	SRB	B100	602115	"	"	20 ci	
7	SRB	B100	602128	"	"	20 ci	
8	SRB	B100	602117	"	"	20 ci	
9	SRB	B100	602119	"	"	20 ci	Box 3
10	SRB	B100	602122	"	"	20 ci	
11	SRB	B100	602121	"	"	20 ci	
12	SRB	B100	602118	"	"	20 ci	
13	SRB	B100	606115	4	97	20 ci	Box 4
14	SRB	B100	606116	4	97	20 ci	
15	SRB	B100	606117	4	97	20 ci	

**The above information should be on the signs labels. If any information on the sign is missing please fill in the fields with "missing" or "illegible", etc. Please print clearly. A double sign is counted as "TWO" signs—not "ONE" Please make note of this.*

Once we have received and processed this information an RMA number will be issued.

If you have more signs that this form holds, please copy additional pages and filling all necessary information.

SERIAL NUMBER SPREADSHEET

Company Name	St. Anthony ID FMU	Date	3/27/15
Address 1	14 W. Main	Isolite RMA #	
Address 2		EWS Order #	FMAID-204679
Address 3		MTS Order #s	FMAID-204678
City/State	Teton ID	Contact Name	Margo Thompson
Zip/Post Code	83451	Contact Phone	208 386 7184
Country	USA	Contact FAX	
		Contact E-mail	Thompsonmve@schuyler.org

	Manufacturer Name	Model No.	Serial No.	Manufacture Date		Activity Include "CI" or "TBq"
				Month	Year	
(16)	SRB	B100	066114	4	97	20g Box 4
2						
3						
4						
5						
6						
7						
8						
9						
10						
11						
12						
13						
14						
15						

**The above information should be on the signs labels. If any information on the sign is missing please fill in the fields with "missing" or "illegible", etc. Please print clearly. A double sign is counted as "TWO" signs—not "ONE" Please make note of this.*

Once we have received and processed this information an RMA number will be issued.

If you have more signs that this form holds, please copy additional pages and filling all necessary information.

SERIAL NUMBER SPREADSHEET

Company Name	St. Anthony ID FM	Date	3/27/17
Address 1	6 N. Teton Ave	Isolite RMA #	
Address 2		EWS Order #	FMAO-204679
Address 3		MTS Order #s	FMAO-204679
City/State	Sugar City, ID	Contact Name	Margo Thompson
Zip/Post Code	83448	Contact Phone	208 356 7184
Country	USA	Contact FAX	
		Contact E-mail	thompsonmv@schuch.org

(17)

	Manufacturer Name	Model No.	Serial No.	Manufacture Date		Activity Include "CI" or "TBq"
				Month	Year	
1	SRB	B100	616109	4	97	Zcci
2						
3						
4						
5						
6						
7						
8						
9						
10						
11						
12						
13						
14						
15						

Box 5

**The above information should be on the signs labels. If any information on the sign is missing please fill in the fields with "missing" or "illegible", etc. Please print clearly. A double sign is counted as "TWO" signs—not "ONE" Please make note of this.*

Once we have received and processed this information an RMA number will be issued.

If you have more signs that this form holds, please copy additional pages and filling all necessary information.

SERIAL NUMBER SPREADSHEET

Company Name	St. Anthony DFM	Date	3/27/17
Address 1	4120 Big Springs	Isolite RMA #	
Address 2	A-FRAME	EWS Order #	FMA40-204679
Address 3		MTS Order #	FMA40-204678
City/State	Macks Inn ID	Contact Name	Margo Thompson
Zip/Post Code	83433	Contact Phone	202 356 7184
Country	USA	Contact FAX	
		Contact E-mail	thompsonmv@dschng.org

	Manufacturer Name	Model No.	Serial No.	Manufacture Date		Activity Include "CI" or "TBq"	
				Month	Year		
1	SRB	B100	616111	4	97	20 ci	Box 5
2	SRB	B100	616123	4	97	20 ci	
3	SRB	B100	616103	4	97	20 ci	
4	SRB	B100	616121	4	97	20 ci	Box 6
5	SRB	B100	616105	4	97	20 ci	
6							
7							
8							
9							
10							
11							
12							
13							
14							
15							

(22)

**The above information should be on the signs labels. If any information on the sign is missing please fill in the fields with "missing" or "illegible", etc. Please print clearly. A double sign is counted as "TWO" signs—not "ONE" Please make note of this.*

Once we have received and processed this information an RMA number will be issued.

If you have more signs that this form holds, please copy additional pages and filling all necessary information.

SERIAL NUMBER SPREADSHEET

6

Company Name	St. Anthony ID FM	Date	3/29/17
Address 1	166 S. 15 th E	Isolite RMA #	
Address 2		EWS Order #	FMAEO-204679
Address 3		MTS Order #s	FMAEO-204678
City/State	Rexburg ID	Contact Name	Margo Thompson
Zip/Post Code	83440	Contact Phone	208 356 7184
Country	USA	Contact FAX	
		Contact E-mail	thompsonmv@dschurch.org

	Manufacturer Name	Model No.	Serial No.	Manufacture Date		Activity Include "Ci" or "TBq"
				Month	Year	
1	SRB	B100	616107	4	97	20 ci
2	SRB	B100	616905	5	97	20 ci
3	SRB	B100	602113	2	96	20 ci
4	SRB	B100	602112	2	96	20 ci
5	SRB	B100	602114	2	96	20 ci
6	SRB	B100	602109	illegible	illegible	20 ci
7						
8						
9						
10						
11						
12						
13						
14						
15						

Box 6
Box 7

28

**The above information should be on the signs labels. If any information on the sign is missing please fill in the fields with "missing" or "illegible", etc. Please print clearly. A double sign is counted as "TWO" signs—not "ONE" Please make note of this.*

Once we have received and processed this information an RMA number will be issued.

If you have more signs that this form holds, please copy additional pages and filling all necessary information.

SERIAL NUMBER SPREADSHEET

Company Name	St. Anthony ID FM	Date	3/29/17
Address 1	4120 Big Springs	Isolite RMA #	
Address 2		EWS Order #	FMACQ-204679
Address 3		MTS Order #s	FMACQ 204678
City/State	Macks Inn, ID	Contact Name	Margo Thompson
Zip/Post Code	83433	Contact Phone	208 356 7184
Country	USA	Contact FAX	
		Contact E-mail	thompsonm@idschuck.org

	Manufacturer Name	Model No.	Serial No.	Manufacture Date		Activity Include "CI" or "TBq"	
				Month	Year		
1	SRB	B100	602108	illegible	illegible	20 ci	Box 8
2	SRB	B100	602111	"	"	20 ci	
3	SRB	B100	616797	5	97	20 ci	
4	SRB	B100	616795	illegible	illegible	20 ci	
5	SRB	B100	616907	6	97	20 ci	Box 9
6	SRB	B100	616798	5	97	20 ci	
7	SRB	B100	616796	5	97	20 ci	
8	SRB	B100	616800	5	97	20 ci	
9	SRB	B100	612953	1	97	20 ci	Box 10
10	SRB	B100	612961	1	97	20 ci	
11	SRB	B100	Missing	Missing			
12	SRB	B100	612965	1	97	20 ci	
13	SRB	B100	612964	1	97	20 ci	Box 11
14	SRB	B100	612956	1	97	20 ci	
15	SRB	B100	612967	1	97	20 ci	

43

*The above information should be on the signs labels. If any information on the sign is missing please fill in the fields with "missing" or "illegible", etc. Please print clearly. A double sign is counted as "TWO" signs—not "ONE" Please make note of this.

Once we have received and processed this information an RMA number will be issued.

If you have more signs that this form holds, please copy additional pages and filling all necessary information.

SERIAL NUMBER SPREADSHEET

Company Name	St. Anthony ID FM	Date	3/29/17
Address 1	4120 Big Springs	Isolite RMA #	
Address 2		EWS Order #	FMACO-204679
Address 3		MTS Order #	FMACO-204678
City/State	Macks Inn ID	Contact Name	Margo Thompson
Zip/Post Code	83433	Contact Phone	208 396 7184
Country	USA	Contact FAX	
		Contact E-mail	thompsonmvp@dschuch.org

	Manufacturer Name	Model No.	Serial No.	Manufacture Date		Activity Include "Ci" or "TBq"
				Month	Year	
1	SRB	B100	612954	1	97	20 ci
2	SRB	B100	616118	4	97	20 ci
3	SRB	B100	616119	4	97	20 ci
4	SRB	B100	616102	4	97	20 ci
5	SRB	B100	616100	4	97	20 ci
6						
7						
8						
9						
10						
11						
12						
13						
14						
15						

48

Box 11
Box 12

**The above information should be on the signs labels. If any information on the sign is missing please fill in the fields with "missing" or "illegible", etc. Please print clearly. A double sign is counted as "TWO" signs—not "ONE" Please make note of this.*

Once we have received and processed this information an RMA number will be issued.

If you have more signs that this form holds, please copy additional pages and filling all necessary information.

6

SERIAL NUMBER SPREADSHEET

Company Name	St. Anthony ID FMU	Date	3/29/17
Address 1	3462 N Salem Rd	Isolite RMA #	
Address 2		EWS Order #	FMACQ-204679
Address 3		MTS Order #s	FMACQ-204678
City/State	Rexburg ID	Contact Name	Margo Thompson
Zip/Post Code	83440	Contact Phone	208 356 7184
Country	USA	Contact FAX	
		Contact E-mail	thompsonm@dschurch.org

	Manufacturer Name	Model No.	Serial No.	Manufacture Date		Activity Include "CI" or "TBq"	
				Month	Year		
1	SRB	B100	616101	4	97	20 ci	Box 13
2	SRB	B100	616124	4	97	20 ci	
3	SRB	B100	616122	4	97	20 ci	
4	SRB	B100	616113	4	97	20 ci	
5	SRB	B100	616108	4	97	20 ci	Box 14
6	SRB	B100	616112	4	97	20 ci	
7	SRB	B100	616110	4	97	20 ci	
8	SRB	B100	616120	4	97	20 ci	
9	SRB	B100	616104	4	97	20 ci	Box 15
10	SRB	B100	616106	4	97	20 ci	
11	SRB	B100	612962	10	97	20 ci	
12	SRB	B100	612956	1	97	20 ci	
13	NRD	T4601	115415	7	97	25 ci	Box 16
14	SRB	B100	612957	1	97	20 ci	
15	SRB	B100	1012960	1	97	20 ci	

(63)

*The above information should be on the signs labels. If any information on the sign is missing please fill in the fields with "missing" or "illegible", etc. Please print clearly. A double sign is counted as "TWO" signs—not "ONE" Please make note of this.

Once we have received and processed this information an RMA number will be issued.

If you have more signs that this form holds, please copy additional pages and filling all necessary information.

8

SERIAL NUMBER SPREADSHEET

Company Name	St. Anthony TD FM	Date	3/24/17
Address 1	3462 N. Salem Rd	Isolite RMA #	
Address 2		EWS Order #	FMACQ-204679
Address 3		MTS Order #s	FMACQ-204678
City/State	Roxbury TD	Contact Name	Margo Thompson
Zip/Post Code	03440	Contact Phone	208 356 7184
Country	USA	Contact FAX	
		Contact E-mail	thompsonmv@dschuch.org

CA

	Manufacturer Name	Model No.	Serial No.	Manufacture Date		Activity Include "CI" or "TBq"
				Month	Year	
1	SRB	B100	612966	1	97	20ci
2						
3						
4						
5						
6						
7						
8						
9						
10						
11						
12						
13						
14						
15						

Box 16

**The above information should be on the signs labels. If any information on the sign is missing please fill in the fields with "missing" or "illegible", etc. Please print clearly. A double sign is counted as "TWO" signs—not "ONE" Please make note of this.*

Once we have received and processed this information an RMA number will be issued.

If you have more signs that this form holds, please copy additional pages and filling all necessary information.