

CATEGORY 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9907300044 DOC. DATE: 99/07/27 NOTARIZED: NO DOCKET #
FACIL: 50-388 Susquehanna Steam Electric Station, Unit 2, Pennsylvania 05000388
AUTH. NAME: BYRAM, R.G. AUTHOR AFFILIATION: Pennsylvania Power & Light Co. *See Report*
RECIP. NAME: RECIPIENT AFFILIATION: Records Management Branch (Document Control Desk)

SUBJECT: Forwards "SSES, Unit 2 Ninth Refueling & Insp Outage ISI Outage Summary Rept." Rept being provided to NRC IAW 1989 Edition of ASME Boiler & Pressure Vessel Code, Div 1, Section XI, Paragraph I WA 6230.

DISTRIBUTION CODE: A047D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1 + 600
TITLE: OR Submittal: Inservice/Testing/Relief from ASME Code

NOTES:

	RECIPIENT	COPIES		RECIPIENT	COPIES	
	ID CODE/NAME	LTTR	ENCL	ID CODE/NAME	LTTR	ENCL
	LPD1-1 LA	1	1	NERSES, V	1	1
INTERNAL:	ACRS	1	1	FILE CENTER 01	1	1
	NUDOCS-ABSTRACT	1	1	OGC/RP	1	0
	RES/DET/ERAB	1	1	RES/DET/MEB	1	1
EXTERNAL:	LITCO ANDERSON	1	1	NOAC	1	1
	NRC PDR	1	1			

MICROFILMED

NOTE TO ALL "RIDS" RECIPIENTS:
PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

TOTAL NUMBER OF COPIES REQUIRED: LTTR 11 ENCL 10

C
A
T
E
G
O
R
Y


1

D
O
C
U
M
E
N
T

RECEIVED
FEB 21 1964

Robert G. Byram
Senior Vice President
Generation and Chief Nuclear Officer
Tel. 610.774.7502 Fax 610.774.5019
E-mail: rgbyram@papl.com

PP&L, Inc.
Two North Ninth Street
Allentown, PA 18101-1179
Tel. 610.774.5151
<http://www.ppl-inc.com/>



JUL 27 1999

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Mail Station OP1-17
Washington, DC 20555

**SUSQUEHANNA STEAM ELECTRIC STATION
UNIT 2 NINTH REFUELING AND INSPECTION OUTAGE
ISI SUMMARY REPORT
PLA-5088**

Docket No 50-388

Attached for your use is a copy of the Susquehanna Steam Electric Station Inservice Inspection Outage Summary Report for the Unit 2 Ninth Refueling and Inspection Outage. This report is being provided to you in accordance with the 1989 Edition of the ASME Boiler and Pressure Vessel Code, Division 1, Section XI, Paragraph I WA 6230. A copy of this report has also been sent to the Commonwealth of Pennsylvania.

If you have any questions, please contact C. T. Coddington at (610) 774-4019.

Sincerely,

A handwritten signature in black ink, appearing to be "R. G. Byram", is written over a horizontal line. The signature is stylized and somewhat cursive.

R. G. Byram

Attachment

copy: NRC Region I
Mr. S. Hansell, NRC Sr. Resident Inspector
Mr. V. Nerses, NRC Sr. Project Manager

11
A047

9907300044 990727
PDR ADDCK 05000388
Q PDR

4. 13

1941

1941

1941

SUSQUEHANNA STEAM ELECTRIC STATION
PP&L, Inc.

UNIT 2 NINTH REFUELING AND INSPECTION OUTAGE

**INSERVICE INSPECTION
OUTAGE SUMMARY REPORT**