

**Open Generic Communication TACs (PA No. 115126)
Summary Report (As Of 5/31/2017)**

TAC NO.	TAC TITLE	AGE (Mon)	TAC OPENED	LEAD ORG
MF3949	RIS 'RIS 2005-29 Rev 1 Anticipated Transients That Could Develop into More Serious Events'	38.0	04/17/2014	DSS
MF4346	RIS 'Pressure Boundary Leakage'	36.0	07/02/2014	NRO
MF5661	RIS 'Safety-Related SSCs in Service Beyond Service Life'	28.0	02/03/2015	PGCB
MF6357	RIS 'Compensatory Measures for Protective Strategy Deficiencies'	24.0	06/16/2015	PGCB
MF7230	RIS 'Identifying and Reporting Human Factor Incidents Under 10 CFR 50.73'	17.0	01/13/2016	PGCB
MF7597	RIS 'Clarifying Appropriate Methods for Resolving Errors in AP1000 Certified Design Information'	13.0	04/20/2016	PGCB
MF8137	RIS 'Licensing Basis Implications of SEP/IPEEE'	10.0	07/19/2016	PGCB
MF8317	RIS 'Status of Issues Identified Through GL 2008-01'	9.0	08/31/2016	PGCB
MF8405	RIS 'NRC Position on the Relationship between General Design Criteria and Technical Specification Operability' (Revision of RIS 2013-05)	8.0	09/22/2016	PGCB
MF8453	RIS 'Functionality of Non-Tech Spec Support Systems as They Relate to Operability of Tech Spec Systems'	7.0	10/11/2016	PGCB
MF9285	IN 'Aluminum High Energy Arc Fault'	3.0	02/16/2017	PGCB
MF9267	IN 'Deficiencies with High Radiation Area Controls'	3.0	02/14/2017	PGCB
MF9353	RIS 'Requests to Dispose of Very Low-Level Radioactive Waste Pursuant to 10 CFR 20.2002, Rev. 1'	3.0	03/02/2017	PGCB
MF9358	RIS 'Human Reliability and Human Performance Database, Rev. 1'	3.0	03/06/2017	PGCB

**Open Generic Communication TACs (PA No. 115126)
Summary Report (As Of 5/31/2017)**

TAC NO.	TAC TITLE	AGE (Mon)	TAC OPENED	LEAD ORG
MF9367	IN 'Potential Binding of Circuit Breaker Anti-Pump Feature'	3.0	03/08/2017	PGCB
MF9405	RIS 'NRC Staff Position on Applying Surveillance Requirements 3.0.2 and 3.0.3 to Administrative Controls Program Tests, Rev. 1'	2.5	03/22/2017	PGCB
MF9464	RIS 'Use of EPRI/NEI Joint Task Force Report, "Guideline on Licensing Digital Upgrades: EPRI TR-102348, Revision 1, NEI 101-01: A Revision of EPRI TR-102348 to Reflect Changes to the 10 CFR 50.59 Rule, Rev. 1'	2.5	03/27/2017	PGCB
MF9558	RIS 'Clarification of Visual Examination Requirements for Reactor Upper Heads to Detect Signs of Leakage	2.0	04/05/2017	PGCB
MF9698	IN 'Anchor/Darling Double Disc Gate Valve Wedge Pin and Stem-Disc Separation Failures'	.5	05/12/2017	PGCB
MF9717	RIS 'Certificate of Compliance Corrections and Revisions'	.2	05/23/2017	PGCB