ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ESSION NBR:8803100054 DOC.DATE: 88/02/26 NOTARIZED: NO DOCKET # FACIL:50-387 Susquehanna Steam Electric Station, Unit 1, Pennsylva 05000387 50-388 Susquehanna Steam Electric Station, Unit 2, Pennsylva 05000388 AUTHOR AFFILIATION AUTH. NAME Region 1, Ofc of the Director JOHNSTON, W.V. RÉCIPIENT AFFILIATION RECIP.NAME KEISER, H.W. Pennsylvania Power & Light Co. SUBJECT: Forwards Safety Insp Repts 50-387/88-01 & 50-388/88-01 on R 880104-08.No violations noted. ENCL DISTRIBUTION CODE: IE01D COPIES RECEIVED:LTR SIZE: TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response D NOTES:1cy NMSS/FCAF/PM. LPDR 2cys Transcripts. 05000387 05000388 8 1cy NMSS/FCAF/PM: LPDR 2cys Transcripts. RECIPIENT COPIES COPIES RECIPIENT ID CODE/NAME LTTR ENCL ID CODE/NAME LTTR ENCL PD1-2 PD 1 THADANI, M 2 1 INTERNAL: AEOD n 1 **DEDRO** NRR MORISSEAU, D NRR/DLPQ/PEB11B NRR/DLPQ/QAB10A 1 NRR/DOEA DIR11E 1 NRR/DREP/EPB10D 1 NRR/DREP/RPB10A 2 2 NRR/DRIS DIR9A2 NRR/PMAS/ILRB12 1 1 1 1 OE_LIEBERMAN,J REG_FILE 02 RGN1 FILE 01 OGC 15-B-18 1 1 1 RES/DRPS DIR 1 02 1 1 01 EXTERNAL: LPDR 2 NRC PDR NSIC 1 1 NOTES: 3 3

R

D

S

/ A

D

D

S

FEB 26 1988

Docket Nos. 50-387 50-388 License Nos. NPF-14 and NPF-22

Pennsylvania Power & Light Company ATTN: Mr. H. W. Keiser Vice President Nuclear Operations 2 North Ninth Street Allentown, Pennsylvania 18101

Gentlemen:

Subject: Combination Inspection Report Nos. 50-387/88-01 and 50-388/88-01

This refers to the routine safety inspection conducted by Mr. A. Finkel of this office on January 4-8, 1988, at Susquehanna Steam Electric Station, Units 1 and 2, Berwick, Pennsylvania of activities authorized by NRC License Nos. NPF-14 and NPF-22 and to the discussions of our findings held by Mr. Finkel with Mr. R. Byram and other members of your staff at the conclusion of the inspection.

Areas examined during this inspection are described in the NRC Region I Inspection Report which is enclosed with this letter. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector.

Within the scope of this inspection, no violations were observed.

No reply to this letter is required. Your cooperation with us in this matter is appreciated.

Sincerely,

ROBERT IN CALLO


William V. Johnston, Acting Director Division of Reactor Safety

Enclosure: NRC Region I Inspection Report Numbers 50-387/88-01 and 50-388/88-01

IEO,

OFFICIAL RECORD COPY

CIR SUSQ 88-01 - 0001.0.0



cc w/encl:

A. R. Sabol, Manager, Nuclear Quality Assurance

E. A. Heckman, Licensing Group Supervisor

R. G. Bryam, Superintendent of Plant-SSES

H. W. Hirst, Manager, Joint Generation Projects Department

R. J. Benich, Services Project Manager, General Electric Company B. D. Kenyon, Senior Vice President-Nuclear

Bryan A. Snapp, Esquire, Assistant Corporate Counsel Herbert D. Woodeshick, Special Office of the President Jesse C. Tilton, III, Allegheny Electric Cooperative Public Document Room (PDR) Local Public Document, Room (LPDR) Nuclear Safety Information Center (NSIC)

NRC Resident Inspector Commonwealth of Pennsylvania

bcc w/encl:

Region I Docket Room (with concurrences) Management Assistant, DRMA (w/o encl)

DRP Section Chief Robert J. Bores, DRSS

TI Coordinator - Bob Summers, PSSC C. Anderson

RI:DRS Finke, a. P. 2.L. 2/3/88 RI:DRS Blumbera