

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM
 REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

SESSION NBR: 8912060412 DOC. DATE: 89/11/22 NOTARIZED: NO DOCKET #
 ACIL: 50-387 Susquehanna Steam Electric Station, Unit 1, Pennsylv 05000387
 50-388 Susquehanna Steam Electric Station, Unit 2, Pennsylv 05000388
 AUTH. NAME AUTHOR AFFILIATION
 BELLAMY, R.R. Region 1, Ofc of the Director
 RECIP. NAME RECIPIENT AFFILIATION
 KEISER, H.W. Pennsylvania Power & Light Co.

SUBJECT: Forwards Insp Repts 50-387/89-28 & 50-388/89-26 on 891016-20 R
 & notice of violation. I

DISTRIBUTION CODE: IE06D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 3413
 TITLE: Environ & Radiological (50 DKT)-Insp Rept/Notice of Violation Respons D

NOTES: LPDR 1 cy Transcripts. 05000387 S
 LPDR 1 cy Transcripts. 05000388

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	
	PD1-2 LA	1 0	PD1-2 PD	1 1	A
	THADANI, M	1 1			D
INTERNAL:	ACRS	2 2	AEOD/ANDERSON, R	1 1	D
	AEOD/DSP	1 1	NMSS/LLOB 5E4	1 1	S
	NMSS/SGDB 4E4	1 1	NRR/DLPQ/LPEB10	1 1	
	NRR/DOEA/OEAB11	1 1	NRR/DREP/PEPB9D	1 1	
	NRR/DREP/PRPB11	2 2	NRR/PMAS/ILRB12	1 1	
	NUDOCS-ABSTRACT	1 1	OGC/HDS2	1 1	
	REG-ELLE 02	1 1	RES	1 1	
	RGN1 DRSS/RPB	1 1	RGN1 FILE 01	1 1	
	RGN4 MURRAY, B	1 1			
EXTERNAL:	EG&G SIMPSON, F	2 2	LPDR	1 1	
	NRC PDR	1 1	NSIC	1 1	
NOTES:		2 2			R

NOV 22 1989

Docket Nos. 50-387
50-388

Pennsylvania Power & Light Company
ATTN: Mr. Harold W. Keiser
Senior Vice President - Nuclear
2 North Ninth Street
Allentown, Pennsylvania 18101

Gentlemen:

Subject: NRC Combined Inspection Report Nos. 50-387/89-28; 50-388/89-26

A routine radiological controls inspection was conducted by Mr. R. L. Nimitz at the Susquehanna Steam Electric Station, Units 1 and 2, on October 16-20, 1989. The inspection concentrated on reviews of radiological controls during the Unit 2 outage. The findings of the inspection were discussed with Mr. R. Byram.

Two apparent violations were identified and are discussed in the enclosed Notice of Violation. The first apparent violation involved failure to adhere to radiation protection procedures. The second apparent violation involved failure to maintain records of radiation surveys. You are required to respond to the enclosed Notice of Violation and should follow the instructions contained therein.

The inspector also identified a problem involving lack of adherence to your confined space entry procedures. Although your staff took corrective actions when this matter was brought to their attention, the failure of personnel to adhere to important safety procedures is a concern to the NRC. Additional management attention to this area may be warranted.

We also identified concerns regarding the maintenance and care of control structure ventilation systems. Your attention is directed to the NRC unresolved items identified in the enclosed report. These findings and other findings detailed in the enclosed report indicate an apparent need for enhanced attention to detail by personnel.

OFFICIAL RECORD COPY

CIR SUS 89-28/26 1 - 0001.0.0
11/21/89

8912060412 891122
PDR ADOCK 05000387

RE 06

NOV 22 1989

Your cooperation with us is appreciated.

Sincerely,

~~Printed Signed By:~~
Ronald R. Bellamy

Ronald R. Bellamy, Chief
Facilities Radiological Safety
and Safeguards Branch
Division of Radiation Safety
and Safeguards

Enclosures:

1. Notice of Violation
2. NRC Combined Inspection Report Nos. 50-387/89-28; 50-388/89-26

cc w/encl:


A. R. Sabol, Manager, Nuclear Quality Assurance
J. M. Kenny, Licensing Group Supervisor
R. G. Bryam, Superintendent of Plant-SSES
S. B. Ungerer, Manager, Joint Generation Projects Department
J. D. Decker, Nuclear Services Manager, General Electric Co.
B. A. Snapp, Esquire, Assistant Corporate Counsel
H. D. Woodeshick, Special Office of the President
J. C. Tilton, III, Allegheny Electric Cooperative, Inc.
Public Document Room (PDR)
Local Public Document Room (LPDR)
Nuclear Safety Information Center (NSIC)
NRC Resident Inspector
Commonwealth of Pennsylvania




Pennsylvania Power
& Light Company

3


bcc w/encl:
Region I Docket Room (with concurrences)
Management Assistant, DRMA (w/o encl)
P. Swetland, DRP
PAO 10 (SALP) Reports Only
M. Thadani, NRR
J. Dyer, EDO


RI:DRSS
Nimitz/mk

11/14/89


RI:DRSS
Pasciak

11/14/89


RI:DRSS
Bellamy

11/24/89

OFFICIAL RECORD COPY

CIR SUS 89-28/26 - 0003.0.0
11/13/89

