

SOLIS

949.443.2290

949.248.8621

940 Calle Negocio, Suite 250

San Clemente, CA 92673

SolisUSA.com

May 26, 2017

**Director of FSME
Attn: GLTS
U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001**

In fulfillment of the requirements of 10 CFR 31.5 (c) 8, we hereby notify you that on *05/25/2017* we transferred the self-luminous exit signs listed on the attached spreadsheet to SRB Technologies Inc. 2580 Landmark Dr, Winston-Salem, NC 27103 North Carolina License # 034-0534-2. As required, for each sign listed on the spreadsheet, we include the name of the manufacturer, model number, and serial number.

If you should have any questions, please contact Nestor Garcia at 949-573-5483

Sincerely,

Nestor Garcia

Encl. 4 inventory sheets



This Serial Number Log must also accompany each box as a packing slip and so must accurately reflect the inventory of EACH box.

Inventory Box Number: 1 of 4

Line	Manufacturer Name	Model Number	Serial Number	Date of Manufacture	Activity (Ci or TBq amount)
1	Isolite Safety Light Corporation	2000	A28474	08/2002	7.5
2	Isolite Safety Light Corporation	2000	A28471	08/2002	7.5
3	Isolite Safety Light Corporation	2000	A28471	08/2002	7.5
4	Isolite Safety Light Corporation	2000	A46038	06/1994	7.5
5	Shield Source Incorporated	2000	Y29030	06/2008	0.278
6	Shield Source Incorporated	2000	Y29029	06/2008	0.278
7	Safety Light Corporation	2000	357870	01/2006	7.5
8	Safety Light Corporation	2000	436656	11/2007	7.5
9	Safety Light Corporation	2000	357885	01/2006	7.5
10	Safety Light Corporation	2000	426972	08/2007	7.5

NG
Initial

5/9/17
Date

Please email this log to sales@tritiumdisposal.com or fax to: 614-863-0622.
Make sure to include your contact info if you have not already been assigned a TritiumDisposal account rep.



This Serial Number Log must also accompany each box as a packing slip and so must accurately reflect the inventory of EACH box.

Inventory Box Number: 2 of 4

Line	Manufacturer Name	Model Number	Serial Number	Date of Manufacture	Activity (Ci or TBq amount)
1	Isolite Safety Light Corporation	2000	A32266	02/1993	7.5
2	Isolite Safety Light Corporation	2000	A391608	09/1993	7.5
3	Isolite Safety Light Corporation	2000	A391607	09/1993	7.5
4	Isolite Safety Light Corporation	2000	A39434	09/1993	7.5
5	Isolite Safety Light Corporation	2000	A55758	05/1995	7.5
6	Isolite Safety Light Corporation	2000	A55759	05/1995	7.5
7	Isolite Safety Light Corporation	2000	A391605	09/1993	7.5
8	Isolite Safety Light Corporation	2000	A55753	05/1995	7.5
9	Isolite Safety Light Corporation	2000	A55760	05/1995	7.5
10	Isolite Safety Light Corporation	2000	A85249	05/1998	7.5

NL
Initial

5/9/17
Date

Please email this log to sales@tritiumdisposal.com or fax to: 614-863-0622.
Make sure to include your contact info if you have not already been assigned a TritiumDisposal account rep.



This Serial Number Log must also accompany each box as a packing slip and so must accurately reflect the inventory of EACH box.


Inventory Box Number: 3 of 4

Line	Manufacturer Name	Model Number	Serial Number	Date of Manufacture	Activity (Ci or TBq amount)
1	Safety Light Corporation	2000	284815	09/2004	9.5
2	Safety Light Corporation	2000	357890	01/2006	7.5
3	Safety Light Corporation	2000	436655	11/2007	7.5
4	Safety Light Corporation	2000	426971	08/2007	7.5
5	Safety Light Corporation	2000	436657	11/2007	7.5
6	Safety Light Corporation	2000	357885	01/2006	7.5
7	Safety Light Corporation	2000	284812	09/2004	9.5
8	Safety Light Corporation	2000	284819	09/2004	9.5
9	Safety Light Corporation	2000	284809	09/2004	9.5
10	Safety Light Corporation	2000	436658	11/2007	7.5

NG
Initial

5/9/17
Date

Please email this log to sales@tritiumdisposal.com or fax to: 614-863-0622.
Make sure to include your contact info if you have not already been assigned a TritiumDisposal account rep.



This Serial Number Log must also accompany each box as a packing slip and so must accurately reflect the inventory of EACH box.

Inventory Box Number: 4 of 4

Line	Manufacturer Name	Model Number	Serial Number	Date of Manufacture	Activity (Ci or TBq amount)
1	Isolite Safety Light Corporation	2000	A39389	09/1993	7.5
2	Isolite Safety Light Corporation	2000	A981251	08/1999	7.5
3	Isolite Safety Light Corporation	2000	A81444	01/1998	7.5
4	Isolite Safety Light Corporation	2000	A32267	02/1993	7.5
5	Isolite Safety Light Corporation	2000	A082204	08/1990	7.0
6	Isolite Safety Light Corporation	2000	A67678	07/1996	7.5
7	Isolite Safety Light Corporation	2000	A55740	05/1995	7.5
8	Isolite Safety Light Corporation	2000	A81439	01/1998	7.5
9	Isolite Safety Light Corporation	2000	A32212	02/1993	7.5
10	Isolite Safety Light Corporation	2000	A81445	01/1998	7.5

NG
Initial

5/9/17
Date

Please email this log to sales@tritiumdisposal.com or fax to: 614-863-0622.
Make sure to include your contact info if you have not already been assigned a TritiumDisposal account rep.