

CATEGORY 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9806240125 DOC. DATE: 98/06/17 NOTARIZED: NO DOCKET #
 FACIL: 50-387 Susquehanna Steam Electric Station, Unit 1, Pennsylva 05000387
 50-388 Susquehanna Steam Electric Station, Unit 2, Pennsylva 05000388
 AUTH. NAME AUTHOR AFFILIATION
 BYRAM, R.G. Pennsylvania Power & Light Co. *See Report*
 RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Forwards revised proprietary occupational radiation exposure repts (NRC Form 5) for exposures received by individuals in CYs 1995 & 97. Calculation error in dose tracking algorithm necessitated revising repts. Proprietary info withheld. C
A

DISTRIBUTION CODE: IE56D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1 + 126 T
 TITLE: Annual Personnel Monitoring Rpt/Annual Rad Exposure Rpt by Functions E

NOTES: 05000387G

	RECIPIENT		COPIES		RECIPIENT		COPIES		
	ID CODE/NAME		LTR	ENCL	ID CODE/NAME		LTR	ENCL	
	PD1-2 PD		1	0	NERSES, V		1	1	O R Y
INTERNAL:	ACNW		1	1	FILE CENTER		1	1	
	NMSS/IMSB T8F5		1	1	NRR/DRPM/PERB/B		2	2	
	RES/DRA/RPHEB		1	1	RGN1 01		1	1	1
INTERNAL:	LITCO BRYCE, J H		1	0	NOAC		1	0	
	NRC PDR		1	0					
NOTES:			1	1					D O C U M E N T

NOTE TO ALL "RIDS" RECIPIENTS:
 PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

TOTAL NUMBER OF COPIES REQUIRED: LTR 13 ENCL 12 ⁹



1/2



Robert G. Byram
Senior Vice President
Generation and Chief Nuclear Officer
Tel. 610.774.7502 Fax 610.774.5019
E-mail: rgbyram@papl.com

PP&L, Inc.
Two North Ninth Street
Allentown, PA 18101-1179
Tel. 610.774.5151
http://www.papl.com/



JUN 17 1998

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Mail Stop P1-137
Washington, D. C. 20555

SUSQUEHANNA STEAM ELECTRIC STATION
REVISED OCCUPATIONAL RADIATION
EXPOSURE REPORTS
PLA-4899 FILE R41-2

Docket Nos. 50-387
and 50-388

Attached are fifty-eight revised Occupational Radiation Exposure Reports (NRC Form 5) for exposures received by individuals in calendar years 1995 and 1997. A calculation error in the dose tracking algorithm necessitated revising fifty-six 1995 reports. This error, which has been corrected, resulted in an underestimation of the Derived Air Concentration (DAC)-hours exposures received by the individuals for the 1995 calendar year. Also, a data import error resulted in incomplete TLD exposure records (data for several TLD's were not entered into the TLD record) for two individuals in 1997. These import errors have also been corrected. To ensure that 1997 exposure records are correct a review of the 1997 imported data was performed and concluded that the data entry error was isolated to the two individuals. No SSES administrative dose level or NRC dose limit was exceeded as a result of the correction to the occupational exposure records. The revised NRC Form 5 reports were sent to the individuals affected.

Please contact J. M. Kenny at 610 774-7535, if you have questions concerning these revised reports.

Sincerely,

R. G. Byram

Attachments

9806240125 980617
PDR ADOCK 05000387
R PDR

copy: NRC Region I
Mr. K. Jenison, NRC Sr. Resident Inspector
Mr. V. Nerses, NRC Sr. Project Manager
REIRS Project Manager

change: LITCO, BRYCE
NIDAC
NRC PDR

Handwritten notes and initials:

JF 5/1

lit	encl.
1	0
1	0
1	0