

# CATEGORY 1

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9807070233 DOC.DATE: 98/06/29 NOTARIZED: NO DOCKET #  
 FACIL:50-387 Susquehanna Steam Electric Station, Unit 1, Pennsylva 05000387  
 AUTH.NAME AUTHOR AFFILIATION  
 KUCZYNSKI,G.J. Pennsylvania Power & Light Co.  
 RECIP.NAME RECIPIENT AFFILIATION  
 Records Management Branch (Document Control Desk)

SUBJECT: Forwards LER 98-011-00,describing unplanned insolation of Unit 1 Div 2 drywell cooling logic during relay replacement evolution.Isolation is considered ESF,per 10CFR50.73.

DISTRIBUTION CODE: IE22T COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 1+3  
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

05000387E

|           | RECIPIENT ID CODE/NAME | COPIES LTR ENCL | RECIPIENT ID CODE/NAME | COPIES LTR ENCL |
|-----------|------------------------|-----------------|------------------------|-----------------|
|           | PD1-2 PD               | 1 1             | NERSES,V               | 1 1             |
| INTERNAL: | ACRS                   | 1 1             | AEOD/SPD/RAB           | 2 2             |
|           | AEOD/SPD/RRAB          | 1 1             | FILE CENTER            | 1 1             |
|           | NRR/DE/ECGB            | 1 1             | NRR/DE/EELB            | 1 1             |
|           | NRR/DE/EMEB            | 1 1             | NRR/DRCH/HICB          | 1 1             |
|           | NRR/DRCH/HOHB          | 1 1             | NRR/DRCH/HQMB          | 1 1             |
|           | NRR/DRPM/PECB          | 1 1             | NRR/DSSA/SPLB          | 1 1             |
|           | NRR/DSSA/SRXB          | 1 1             | RES/DET/EIB            | 1 1             |
|           | RGN1 FILE 01           | 1 1             |                        |                 |
| EXTERNAL: | L ST LOBBY WARD        | 1 1             | LITCO BRYCE,J H        | 1 1             |
|           | NOAC POORE,W.          | 1 1             | NOAC QUEENER,DS        | 1 1             |
|           | NRC PDR                | 1 1             | NUDOCS FULL TXT        | 1 1             |
| NOTES:    |                        | 1 1             |                        |                 |

**THIS DOCUMENT HAS BEEN SCANNED**

NOTE TO ALL "RIDS" RECIPIENTS:


PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED  
 TOTAL NUMBER OF COPIES REQUIRED: LTR 25 ENCL 25

C  
A  
T  
E  
G  
O  
R  
Y  
1  
D  
O  
C  
U  
M  
E  
N  
T

George J. Kuczynski  
General Manager-Susquehanna

Susquehanna Steam Electric Station  
P.O. Box 467, Berwick, PA 18603  
Tel. 717.542.3120 Fax 717.542.1949



June 29, 1998

U.S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Mail Station P1-137  
Washington, DC 20555

SUSQUEHANNA STEAM ELECTRIC STATION  
LICENSEE EVENT REPORT 50-387/98-011-00  
PLA - 0004934 FILE R41-2

Docket No. 50-387  
License No. NPF-14

Attached is Licensee Event Report 50-387/98-011-00. This report describes an unplanned isolation of the Unit 1 Division 2 Drywell Cooling logic during a relay replacement evolution. PP&L is considering this isolation an Engineering Safety Feature (ESF) invalid actuation, reportable per 10CFR50.73(a)(2)(iv). PP&L has concluded that no valid ESF signals occurred nor were there any plant conditions which would require a containment isolation. The unit was in its 10th Refueling Outage at the time of the event.

G. J. Kuczynski  
General Manager - Susquehanna SES

Attachment

cc: Mr. H. J. Miller  
Regional Administrator  
U. S. Nuclear Regulatory Commission  
475 Allendale Road  
King of Prussia, PA 19406

cc: Mr. Kenneth M. Jenison  
Sr. Resident Inspector  
U.S. Nuclear Regulatory Commission  
P. O. Box 35  
Berwick, PA 18603-0035

9807070233 980629  
PDR ADOCK 05000387  
S PDR

103