

From: [John & Martha Tanner](#)
To: [RulemakingComments.Resource](#)
Subject: [External_Sender] Docket ID NRC-2015-0225
Date: Tuesday, June 20, 2017 8:37:58 AM

The extent of planning zones around nuclear facilities should be proportional to the risk. This includes the amount of nuclear material being handled, and the conditions which could allow it to spread. The conditions include pressure and temperature as well as containment measures. As an extreme example, the exclusion zone around an individual working with radioactive material in a laboratory is very minimal, not ten miles.

John Tanner, Idaho Falls, ID