



Commonwealth Edison
Dresden Nuclear Power Station
R.R. #1
Morris, Illinois 60450
Telephone 815/942-2920


October 17, 1978

BBS Ltr. #78-1369

James G. Keppler, Regional Director
Directorate of Regulatory Operations - Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

REGULATORY DOCKET FILE COPY

Reportable Occurrence Report #78-037/03L-0, Docket #050-249 is hereby submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.2.(d), abnormal degradation of systems other than those specified in item B.1.e. designed to contain radioactive material resulting from the fission process.


B.B. Stephenson
Station Superintendent
Dresden Nuclear Power Station

BBS/deb

Enclosure

cc: Director of Inspection & Enforcement
Director of Management Information & Program Control
File/NRC

REGULATORY DOCKET FILE COPY

7810240136

A002
5/11