

Wagner, Katie

From: Jonathan Krowisz <jonathankrowisz@kirco.com>
Sent: Tuesday, June 20, 2017 8:58 AM
To: Wagner, Katie
Subject: [External_Sender] Transfer Letter
Attachments: transfer letter.pdf

Hi Katie,

I was told you handle transfer letters for self luminous signs. Please see the attached letter notifying the USNRC of transfer. Please let me know if I need to do anything else.



JONATHAN KROWISZ |
1155 Brewery Park Blvd | Detroit, MI 48207
O 313.259.8526

GILTS

Jonathan Krowisz
Brewery Park Realty Group, LLC c/o KIRCO Management Services, LLC
1155 Brewery Park Blvd.
Detroit, MI 48207
313-259-8526
jkrowisz@kirco.com
June 20, 2017

Katie Wagner
United States Nuclear Regulatory Commission
Washington, DC 20555-0001

Dear Katie Wagner :

This is to inform you that the following self luminous exit sign was transferred to ISOLITE Corporation using their RGA# 12832PA-RMA. Isolite received the shipment of the self luminous sign on 4/26/2017.

Manufacturer: Isolite

Manufacturer Date 1317

Model Number SLX 60SR10B

Serial Number H79599

Original Activity: .281 Tbq

Thank you for your prompt attention to this matter. Please let me know if you need any more information from me.

Sincerely,



Jonathan Krowisz

Administrative Assistant



Jonathan Krawisz

Serial Number Spreadsheet

| | | | |
|--------------|--------------------------------|---------------|--------------------|
| Company Name | Brewery Park Realty Group, LLC | Contact Name | Jonathan Krawisz |
| Address 1 | 1155 Brewery Park Blvd. | Contact Phone | 313-259-8526 |
| Address 2 | | Contact Fax | 313-259-8538 |
| City/State | Detroit | Contact Email | j.krawisz@krcb.com |
| Zip Code | 48207 | Today's Date | 4/19/17 |

*Please completely fill out the above fields

| Line | Manufacturer Name | Manufacturer Date | Model Number | Serial Number | Original Activity (Ci or Tbq) |
|------|-------------------|-------------------|--------------|---------------|-------------------------------|
| 1 | Isolite | 1317 | S-LX60SR10B | H79599 | -281 Tbq |
| 2 | | | | | |
| 3 | | | | | |
| 4 | | | | | |
| 5 | | | | | |
| 6 | | | | | |
| 7 | | | | | |
| 8 | | | | | |
| 9 | | | | | |
| 10 | | | | | |
| 11 | | | | | |
| 12 | | | | | |
| 13 | | | | | |
| 14 | | | | | |
| 15 | | | | | |
| 16 | | | | | |
| 17 | | | | | |
| 18 | | | | | |
| 19 | | | | | |
| 20 | | | | | |
| 21 | | | | | |
| 22 | | | | | |
| 23 | | | | | |
| 24 | | | | | |
| 25 | | | | | |

*The above information should be on the signs labels. If any information on the sign is missing please fill in the fields with "missing" or "illegible", etc. Please print clearly. A double sign is counted as "TWO" signs, not "ONE" Please make note of this. The company & address information, should belong to the End-User (location the signs have physically been removed from).



Department of Transportation Training & Acknowledgement
For the transfer of Self Luminous EXIT signs

- Self Luminous EXIT signs are illuminated with internal light sources powered by tritium gas. Tritium gas is a radioactive isotope of hydrogen. For this reason, Federal Regulations require that any person shipping this product must have training sufficient to comply with US Department of Transportation regulations in the Code of Federal Regulations #49 Part 172.
- To receive this training, the shipper must read, understand and perform the following steps. Also comply with all instructions contained in "Isolite Packaging Instructions". Place a check mark in each box after completing then sign and date this form.
- Keep this completed form in your files for at least three years in case of regulatory inspection.

- A sturdy cardboard box will be sufficient to ship the signs because they meet the general package design requirements of 49 CFR 173.410.
- The EXIT signs are to be shipped as "UN2911- excepted packages for radioactive instruments and articles (49 CFR 173.424)." **The total amount of tritium to be placed in each box, must not exceed 99.99 Ci (curies) or 3.663 TBQ (terabecquerels). Please add up the total Ci or TBQ content of each box. The total amount of tritium, per shipment must not exceed 999.99 curies tritium, or 36.99963 TBQ.**
- You must ensure that the active materials (the glowing inner tubes) are completely enclosed by non-active components (the sign housing). Each sign must be visually inspected to ensure that it is not crushed or punctured in any way that might cause the inner tubes to be broken.
- If a transportation incident occurs, you must report the incident to the US DOT per 49 CFR 171.15 and 49 CFR 171.16.

***Please Note: Any signs broken and/or contaminated due to failure to comply with DOT regulation or Isolite Packaging Instructions will be sent, per law, for burial. The shipment generator agrees to be financially responsible for any and all additional costs.**

Jonathan Krowisz
Name
Brewery Park Realty Group
Company
[Signature]
Signature

313-259-8526
Phone Number
jkrowisz@kisco.com
Email Address
4-12-17
Date

6/20/2017

Tracking: UPS



Proof of Delivery

Close Window

Dear Customer,

This notice serves as proof of delivery for the shipment listed below.

| | |
|---------------------------|----------------------|
| Tracking Number: | 1Z6A889E0349398286 |
| Service: | UPS Ground |
| Weight: | 3.90 lbs |
| Shipped/Billed On: | 04/24/2017 |
| Delivered On: | 04/26/2017 1:15 P.M. |
| Delivered To: | BERWYN, PA, US |
| Received By: | MARTIN |
| Left At: | Receiver |

Thank you for giving us this opportunity to serve you.

Sincerely,

UPS

Tracking results provided by UPS: 06/20/2017 8:44 A.M. ET