



Commonwealth Edison
Dresden Nuclear Power Station
R.R. #1
Morris, Illinois 60450
Telephone 815/942-2920

March 28, 1979

BBS LTR #79-271

James G. Keppler, Regional Director
Directorate of Regulatory Operations - Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Reportable Occurrence Report #79-04/03L-0, Docket #050-249 is hereby submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.2.(c), observed inadequacies in the implementation of administrative or procedural controls which threaten to cause reduction of degree of redundancy provided in reactor protection systems or engineered safety feature systems.

A handwritten signature in cursive script, appearing to read 'B. B. Stephenson'.

B. B. Stephenson
Superintendent

~~Dresden Nuclear Power Station~~

BBS:lbg

Enclosure

cc: Director of Inspection & Enforcement
Director of Management Information & Program Control
File/NRC

7904060 329

A002
5/11

S