



Commonwealth Edison
Dresden Nuclear Power Station
R.R. #1
Morris, Illinois 60450
Telephone 815/942-2920

DSB

October 10, 1979

BBS LTR #79-805

James G. Keppler, Regional Director
Directorate of Regulatory Operations - Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Reportable Occurrence Report 79-049/03L-0, Docket #050-237 is hereby submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.2(C), observed inadequacies in the implementation of administrative or procedural controls which threaten to cause reduction of degree of redundancy provided in reactor protection systems or engineered safety feature systems.

B. R. Shelton for 10/12

B.B. Stephenson
Station Superintendent
Dresden Nuclear Power Station

BBS:lcg

Enclosure

cc: Director of Inspection & Enforcement
Director of Management Information & Program Control
File/NRC

OCT 16 1979

*1002
5/11*

7910180371