

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 I L D R S 3 00 - 000000 - 000 41111 5

CON'T REPORT SOURCE L 05000249 092379 8102279 9

02 While reversing condenser circulating water flow, the SJAE suction valve 3-5401-B
03 failed to close. This event was of minimal safety significance since the reactor was
04 in a cold shutdown condition. This is the first occurrence of this type at Dresden.
05
06
07
08

09 M B 11 E 12 A 13 V A L V O P 14 E 15 Z 16
17 LER/RO REPORT NUMBER 79 026 03 L 0
18 A 19 Z 20 Z 21 Z 22 0000 23 N 24 N 25 N 26 A 499 26

10 Upon investigation it was determined that the ASCO solenoid valve had failed. The
11 solenoid valve was replaced and condenser circulating water flow was reversed two
12 times and the valve operated satisfactorily. No further action is necessary.
13
14

15 G 28 0000 29 NA 30 A 31 Condenser flow reversal 32
16 Z 33 Z 34 NA 35 NA 36
17 0000 37 Z 38 NA 39
18 0000 40 NA 41
19 Z 42 NA 43
20 N 44 NA 45

7910300173