

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1	I	L	D	R	S	3	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5	
8	9					14	15											25	26					30		57	CAT	58
LICENSEE CODE						LICENSE NUMBER												LICENSE TYPE										

ON'T

REPORT SOURCE: L 6 0 5 0 0 0 2 4 9 7 1 1 0 1 7 9 8 1 1 2 8 7 9 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

2 During normal operations, surveillance DOS 700-4 found IRM #11 to have Rod Block and

3 Hi-Hi-Half Scram Trips to be greater (109/122) than Tech Spec limit on Table 3.2.3

4 (≤ 108) and 3.2.1 (≤ 120). This was of minimal safety significance since the re-

5 maining channels in the "A" safety system, and all channels in the "B" safety system

6 were tested and proved to be operable. There was no effect on public health or safety.

7 This is the first occurrence of this type at Dresden.

08		9		SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE	
09		8		I A 11		E 12		B 13		I N S T R U 14				S 15		Z 16	
8		9		9 10		11		12		13 18				19		20	
17		LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.					
18		7 9		21 22		0 5 4		24 26		0 3		28 29		30 31		32	
33		X 18		Z 19		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER	
34		35		Z 20		36		Z 21		0 0 0 22		N 23		N 24		N 25	
37		40		41		42		43		44		45		46		47	
48		49		50		51		52		53		54		55		56	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The problem was dirty contacts on selector switch 755-302A, model 194X672G7. The
1 1 contacts of the IRM/APRM selector switch were cleaned. IRM #11 was tested satis-
1 2 factorily without adjustment, and returned to service. DOS 700-4 will continue to be
1 3 done weekly.

1 4

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION					
1	5	E	28	0	6	9	29	N/A	30	B	31	Instrument Mechanic Observation	32

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)
1 6 Z (33) Z (34) NA
8 9 10 11 44

LOCATION OF RELEASE (36)
NA
45 80

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37)	Z	(38)	NA	(39)

PERSONNEL INJURIES									
NUMBER				DESCRIPTION (41)					
1	2	3	4	5	6	7	8	9	10
0	0	0	40	NA					

LOSS OF OR DAMAGE TO FACILITY		(43)
TYPE	DESCRIPTION	
1 9 Z (42)	NA	7912030 166

ISSUED: 2 0 8 9 N 44 (45) PUBLICITY DESCRIPTION: NA 68 NRC USE ONLY 69 70

NAME OF PREPARER P. Holland

PHONE. X-489