



Commonwealth Edison
Dresden Nuclear Power Station
R.R. #1
Morris, Illinois 60450
Telephone 815/942-2920

DSB

January 30, 1980

BBS Ltr. #80-65

James G. Keppler, Regional Director
Directorate of Regulatory Operations - Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Reportable Occurrence Report #80-2/03L-0, Docket #050-237 is being submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.2.(c), observed inadequacies in the implementation of administrative or procedural controls which threaten to cause reduction of degree of redundancy provided in reactor protection systems or engineered safety feature systems.

B. B. Stephenson for
1/31

B. B. Stephenson
Station Superintendent
Dresden Nuclear Power Station

BBS:nh

Enclosure

cc: Director of Inspection & Enforcement
Director of Management Information & Program Control
File/NRC

A602
S
1/1

FEB 5 1980

8002080 567

104