

RELATED CORRESPONDENCE

DOCKET NUMBER 50-232/249
PROC & UTIL. FAC.


ISHAM, LINCOLN & BEALE
COUNSELORS AT LAW

ONE FIRST NATIONAL PLAZA FORTY-SECOND FLOOR
CHICAGO, ILLINOIS 60603
TELEPHONE 312-558-7500 TELEX: 2-5288

WASHINGTON OFFICE
1120 CONNECTICUT AVENUE, N.W.
SUITE 325
WASHINGTON, D.C. 20036
202-833-9730

December 11, 1980

Ms. Mary Jo Murray
Assistant Attorney General
Environmental Control Division
Room 2315
188 West Randolph Street
Chicago, Illinois 60604



Re: Dresden Spent Fuel

Dear Mary Jo:

On December 3, 1980 you asked Commonwealth Edison to produce an internal Quadrex/NSC audit report written sometime in 1980 by a man named Henry Thailer. After talking with your expert, Mr. Hubbard, we were able to locate the document you were referring to. It is a 10-page report dated April 4, 1980 from J. Weber, Audit Team Leader, to J. Goldin (both of Quadrex/NSC) entitled: "Internal Audit of LaSalle Pipe Stress Analysis and Support Design (SAR-0303)--Internal Audit Report Number 80-3." Mr. Thailer was a member of the audit team. As the name implies, this internal audit relates to Commonwealth Edison's LaSalle County Nuclear Power Plant, presently under construction. It contains no reference to the Dresden spent fuel rack job. Further, I am informed by Jim Gilcrest and Walt Shewski that the Quadrex/NSC project group working on the LaSalle piping project is entirely separate from the group working on the Dresden racks.

After careful review and discussion with Mr. Gilcrest and Mr. Shewski, we have concluded that this document is not relevant to the Dresden spent fuel rack proceeding, nor is it reasonably calculated to lead to the discovery of relevant material. Accordingly, we will not provide this document to you pursuant to our agreement on informal discovery.

Sincerely,

Philip Steptoe

Philip Steptoe
DS03
s
1/0

PS/kb

CC: Service List

8012160332

G