



Commonwealth Edison
 Dresden Nuclear Power Station
 R.R. #1
 Morris, Illinois 60450
 Telephone 815/942-2920

DSB

December 30, 1980

DJS LTR #80-349

James G. Keppler, Regional Director
 Directorate of Regulatory Operations - Region III
 U.S. Nuclear Regulatory Commission
 799 Roosevelt Road
 Glen Ellyn, IL 60137

US NRC
 DISTRIBUTION SERVICES
 BRANCH

1981 JAN 5 PM 12 51

U.S. NUCLEAR REGULATORY COMMISSION
 DISTRIBUTION SERVICES UNIT

Reportable Occurrence Report #80-47/01T-0, Docket #050-249 is being submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.1.(f), personnel error or procedural inadequacy which prevents or could prevent, by itself, the fulfillment of the functional requirements of systems required to cope with accidents analyzed in the SAR.

D. J. Scott
 Station Superintendent
 Dresden Nuclear Power Station

DJS:lg

Enclosure

cc: Director of Inspection & Enforcement
 Director of Management Information & Program Control
 U.S. NRC, Document Mgt Branch
 File/NRC

8101060467

S

JAN 02 1981

*ADD 2
 3
 11*