

GLTS

**STUECKER ELECTRIC, INC.**  
**P.O. BOX 367**  
**ELIZABETHTOWN, KY 42702**  
**(270) 769-6689**  
**FAX: (270) 737-1442**

# Memo

**To:** DIRECTOR, OFFICE OF FSMEMP

**From:** PAUL STUECKER

**Date:** June 12, 2017

**Re:**

---

I have mailed this packet two times to you and it has been returned both times (see enclosed envelope). I mailed it on 5/12/17 and 5/31/17. One time I didn't put enough postage the other time the post office changed the zip code and it was incorrect.

**STUECKER ELECTRIC, INC.**  
**P.O. BOX 367**  
**ELIZABETHTOWN, KY 42702**  
**(270) 769-6689**

May 12, 2017


Director of FSME  
Attn: GLTS  
U. S. Nuclear Regulatory Commission  
Washington, DC 20555-0001

To Whom It May Concern:

In fulfillment of the requirements of 10 CFR 31.5 (c) 8, we hereby notify you that on May 4, 2017 we transferred the self-luminous exit signs listed on the attached spreadsheet to SRB Technologies, Inc., 2580 Landmark Dr., Winston-Salem, NC 27103; North Carolina License #034-0534-2. As required, for each sign listed on the spreadsheet, we include the name of the manufacturer, model number and serial number.

These were removed from Rineyville Elementary School, 275 Rineyville School Road, Rineyville, KY 40162.

If you should have questions, please contact Paul Stuecker at 270-769-6689.



Sincerely,  
Paul Stuecker  
President

Encl.



This Serial Number Log must also accompany each box as a packing slip and so must accurately reflect the inventory of EACH box.

Inventory Box Number: 1 of 6

Line	Manufacturer Name	Model Number	Serial Number	Date of Manufacture	Activity (Ci or TBq amount)
1	SAFETY LIGHT CORP.	2040	405290	4/2007	7.5 CURIES TRITIUM H3
2	SAFETY LIGHT CORP.	2040	405263	4/2007	7.5 CURIES TRITIUM H3
3	SAFETY LIGHT CORP.	2040	405269	4/2007	7.5 CURIES TRITIUM H3
4	SAETY LIGHT CORP.	2040	405284	4/2007	7.5 CURIES TRITIUM H3
5	SAFETY LIGHT CORP.	2040	405270	4/2007	7.5 CURIES TRITIUM H3
6	SAFETY LIGHT CORP.	2040	405273	4/2007	7.5 CURIES TRITIUM H3
7	SAFETY LIGHT CORP.	2040	405292	4/2007	7.5 CURIES TRITIUM H3
8	SAFETY LIGHT CORP.	2040	405260	4/2007	7.5 CURIES TRITIUM H3
9	SAFETY LIGHT CORP.	2040	405299	4/2007	7.5 CURIES TRITIUM H3
10	SAFETY LIGHT CORP.	2040	405258	4/2007	7.5 CURIES TRITIUM H3

PS

Initial

04/20/17

Date

Please email this log to [sales@tritiumdisposal.com](mailto:sales@tritiumdisposal.com) or fax to: 614-863-0622.

Make sure to include your contact info if you have not already been assigned a TritiumDisposal account rep.



This Serial Number Log must also accompany each box as a packing slip and so must accurately reflect the inventory of EACH box.

Inventory Box Number: 2 of 6

Line	Manufacturer Name	Model Number	Serial Number	Date of Manufacture	Activity (Ci or TBq amount)
1	SAFETY LIGHT CORP.	2040	405287	4/2007	7.5 CURIES TRITIUM H3
2	SAFETY LIGHT CORP.	2040	405288	4/2007	7.5 CURIES TRITIUM H3
3	SAFETY LIGHT CORP.	2040	405285	4/2007	7.5 CURIES TRITIUM H3
4	SAETY LIGHT CORP.	2040	405289	4/2007	7.5 CURIES TRITIUM H3
5	SAFETY LIGHT CORP.	2040	405261	4/2007	7.5 CURIES TRITIUM H3
6	SAFETY LIGHT CORP.	2040	405279	4/2007	7.5 CURIES TRITIUM H3
7	SAFETY LIGHT CORP.	2040	405298	4/2007	7.5 CURIES TRITIUM H3
8	SAFETY LIGHT CORP.	2040	405283	4/2007	7.5 CURIES TRITIUM H3
9	SAFETY LIGHT CORP.	2040	405282	4/2007	7.5 CURIES TRITIUM H3
10	SAFETY LIGHT CORP.	2040	405291	4/2007	7.5 CURIES TRITIUM H3

PS

Initial

04/20/17

Date

Please email this log to [sales@tritiumdisposal.com](mailto:sales@tritiumdisposal.com) or fax to: 614-863-0622.  
Make sure to include your contact info if you have not already been assigned a TritiumDisposal account rep.



This Serial Number Log must also accompany each box as a packing slip and so must accurately reflect the inventory of EACH box.

Inventory Box Number: 3 of 6

Line	Manufacturer Name	Model Number	Serial Number	Date of Manufacture	Activity (Ci or TBq amount)
1	SAFETY LIGHT CORP.	2040	405293	4/2007	7.5 CURIES TRITIUM H3
2	SAFETY LIGHT CORP.	2040	405278	4/2007	7.5 CURIES TRITIUM H3
3	SAFETY LIGHT CORP.	2040	405274	4/2007	7.5 CURIES TRITIUM H3
4	SAETY LIGHT CORP.	2040	405272	4/2007	7.5 CURIES TRITIUM H3
5	SAFETY LIGHT CORP.	2040	405257	4/2007	7.5 CURIES TRITIUM H3
6	SAFETY LIGHT CORP.	2040	405268	4/2007	7.5 CURIES TRITIUM H3
7	SAFETY LIGHT CORP.	2040	405295	4/2007	7.5 CURIES TRITIUM H3
8	SAFETY LIGHT CORP.	2040	405286	4/2007	7.5 CURIES TRITIUM H3
9	SAFETY LIGHT CORP.	2040	405262	4/2007	7.5 CURIES TRITIUM H3
10	SAFETY LIGHT CORP.	2040	405277	4/2007	7.5 CURIES TRITIUM H3

PS

Initial

04/20/17

Date

Please email this log to [sales@tritiumdisposal.com](mailto:sales@tritiumdisposal.com) or fax to: 614-863-0622.  
Make sure to include your contact info if you have not already been assigned a TritiumDisposal account rep.



This Serial Number Log must also accompany each box as a packing slip and so must accurately reflect the inventory of EACH box.

Inventory Box Number: 4 of 6

Line	Manufacturer Name	Model Number	Serial Number	Date of Manufacture	Activity (Ci or TBq amount)
1	SAFETY LIGHT CORP.	2040	251910	2/2004	7.5 CURIES TRITIUM H3
2	SAFETY LIGHT CORP.	2040	405276	4/2007	7.5 CURIES TRITIUM H3
3	SAFETY LIGHT CORP.	2040	405281	4/2007	7.5 CURIES TRITIUM H3
4	SAETY LIGHT CORP.	2040	405264	4/2007	7.5 CURIES TRITIUM H3
5	SAFETY LIGHT CORP.	2040	405271	4/2007	7.5 CURIES TRITIUM H3
6	SAFETY LIGHT CORP.	2040	405296	4/2007	7.5 CURIES TRITIUM H3
7	SAFETY LIGHT CORP.	2040	405297	4/2007	7.5 CURIES TRITIUM H3
8	SAFETY LIGHT CORP.	2040	405267	4/2007	7.5 CURIES TRITIUM H3
9	SAFETY LIGHT CORP.	2040	405294	4/2007	7.5 CURIES TRITIUM H3
10	SAFETY LIGHT CORP.	2040	405259	4/2007	7.5 CURIES TRITIUM H3

PS

Initial

04/20/17

Date

Please email this log to [sales@tritiumdisposal.com](mailto:sales@tritiumdisposal.com) or fax to: 614-863-0622.

Make sure to include your contact info if you have not already been assigned a TritiumDisposal account rep.



This Serial Number Log must also accompany each box as a packing slip and so must accurately reflect the inventory of EACH box.

Inventory Box Number: 5 of 6

Line	Manufacturer Name	Model Number	Serial Number	Date of Manufacture	Activity (Ci or TBq amount)
1	SAFETY LIGHT CORP.	2040 DOUBLE LIGHT	405303	4/2007	15 CURIES TRITIUM H3
2	SAFETY LIGHT CORP.	2040 DOUBLE LIGHT	405305	2/2004	15 CURIES TRITIUM H3
3	SAFETY LIGHT CORP.	2040 DOUBLE LIGHT	405301	4/2007	15 CURIES TRITIUM H3
4	SAFETY LIGHT CORP.	2040 DOUBLE LIGHT	405300	4/2007	15 CURIES TRITIUM H3
5	SAFETY LIGHT CORP.	2040 DOUBLE LIGHT	405302	4/2007	15 CURIES TRITIUM H3
6					
7					
8					
9					
10					

PR  
Initial

04/20/17  
Date

Please email this log to [sales@tritiumdisposal.com](mailto:sales@tritiumdisposal.com) or fax to: 614-863-0622.  
Make sure to include your contact info if you have not already been assigned a TritiumDisposal account rep.



This Serial Number Log must also accompany each box as a packing slip and so must accurately reflect the inventory of EACH box.

Inventory Box Number: 6 of 6

Line	Manufacturer Name	Model Number	Serial Number	Date of Manufacture	Activity (Ci or TBq amount)
1	SAFETY LIGHT CORP.	2040 DOUBLE LIGHT	405306	4/2007	15 CURIES TRITIUM H3
2	SAFETY LIGHT CORP.	2000	252173	2/2004	9.5 CURIES TRITIUM H3
3	SAFETY LIGHT CORP.	2040	405275	4/2007	7.5 CURIES TRITIUM H3
4	SAFETY LIGHT CORP.	2040	405280	4/2007	7.5 CURIES TRITIUM H3
5	SAFETY LIGHT CORP.	2040 DOUBLE LIGHT	405304	4/2007	15 CURIES TRITIUM H3
6					
7					
8					
9					
10					

PR

Initial

04/20/17

Date

Please email this log to [sales@tritiumdisposal.com](mailto:sales@tritiumdisposal.com) or fax to: 614-863-0622.  
Make sure to include your contact info if you have not already been assigned a TritiumDisposal account rep.