



Commonwealth Edison
Dresden Nuclear Power Station
6500 North Dresden Road
Morris, Illinois 60450
Telephone 815/942-2920

June 29, 1993

GFS PMLTR 93-0005

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Licensee Event Report 93-003-01, Docket 050249. This revised report is being submitted to provide an update on progress regarding this event and correct typing errors.

Gary F. Spedl
Gary F. Spedl
Station Manager
Dresden Station

GFS/slb

Enclosure

cc: J. Martin, Regional Administrator, Region III
NRC Resident Inspector's Office
File/NRC
File/Numerical

660052
9307060292 930629
PDR ADOCK 05000249
S PDR

JEJ

DAP FORM 02-08C
SUPPLEMENTAL REPORT TO LER

| | | | | | | |
|--|------|------|------|--------------------|--------------------|---------|
| DVR NO. | | | | | SYSTEM AFFECTED | |
| | STA | UNIT | YEAR | NO. | 1300 | |
| D | - 12 | - 3 | - 93 | - 003 | | |
| <u>PART 1</u> TITLE OF EVENT | | | | <u>OCCURRED</u> | | |
| Isolation Condenser Group V Isolation Due to Spurious Flow Spikes. | | | | 01/17/93 | 0111 | |
| | | | | DATE | TIME | |
| REASON FOR SUPPLEMENTAL REPORT | | | | | | |
| This supplemental report provides an update progress regarding this event and correct typing errors. | | | | | | |
| <u>PART 2</u> | | | | | | |
| ACCEPTANCE BY STATION REVIEW | | | | <i>[Signature]</i> | <i>[Signature]</i> | |
| DATE | | | | 6/25/93 | 6-28-93 | |
| SUPPLEMENTAL REPORT APPROVED AND AUTHORIZED FOR DISTRIBUTION | | | | <i>[Signature]</i> | | 6-30-93 |
| | | | | STATION MANAGER | DATE | |