




Commonwealth Edison
Dresden Nuclear Power Station
6500 North Dresden Road
Morris, Illinois 60450
Telephone 815/942-2920

September 17, 1993

GFSLTR 93-0071

U. S. Nuclear Regulatory Commission
Document Control Clerk
Washington, D.C. 20555

Licensee Event Report #93-002-1, Docket #050237 is being submitted as required by Technical Specification 6.6, NUREG 1022 and 10 CFR 50.73(a) (2) (i) (A). This revised report provides an update on final local leakage rate testing results and corrective actions performed during the D2R13 Refuel Outage to reduce leakage from primary containment.


Gary F. Spedl
Station Manager
Dresden Station

GFS/slb

enclosure

cc: J. Martin, Regional Administrator, Region III
File/NRC
File/Numerical

200181
9309210290 930917
PDR ADOCK 05000237
S PDR

JEZ