



**Commonwealth Edison**  
Dresden Nuclear Power Station  
6500 North Dresden Road  
Morris, Illinois 60450  
Telephone 815/942-2920


August 5, 1994

GFSLTR 94-0261

U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D. C. 20555

Licensee Event Report 94-005<sup>1</sup>-01, Docket 05000237<sup>249</sup>, is being submitted in accordance with Technical Specification 6.6, NUREG 1022 and 10CFR50.73(a)(2)(iv). This supplement is being issued with added corrective actions as required after engineering evaluation.

Sincerely,

  
Gary F. Spedl  
Station Manager  
Dresden Station

GFS/MB:cfq

Enclosure

cc: J. Martin, Regional Administrator, Region III  
NRC Resident Inspector's Office  
File/NRC  
File/Numerical

100109  
9409020298 940805  
PDR ADOCK 05000249  
S PDR  
S



DAP FORM 02-08C  
 SUPPLEMENTAL REPORT TO LER

DVR NO.				SYSTEM AFFECTED	
D	- 12	- 3	- 94	- 001-01	
<u>PART 1</u> TITLE OF EVENT				<u>OCCURRED</u>	
Containment Atmosphere Monitor Check Valve 3-2499-28B Exceeded Technical Specification Leakage Limit of 0.6 L <sub>s</sub> Due to Foreign Materials on Seat				02/26/94	1330
				DATE	TIME
REASON FOR SUPPLEMENTAL REPORT					
Added corrective actions as required after engineering evaluation.					
<u>PART 2</u>					
ACCEPTANCE BY STATION REVIEW				_____	
DATE				_____	
SUPPLEMENTAL REPORT APPROVED AND AUTHORIZED FOR DISTRIBUTION				*See attached DAP 10-01 Rev 16 Form 10-1A and 10-1B for Approval	
				Signatures _____	
				STATION MANAGER _____	
				DATE _____	