

Commonwealth Edison Company
Dresden Generating Station
6500 North Dresden Road
Morris, IL 60450
Tel 815-942-2920



July 21, 1995

TPJLTR 95-0081

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D. C. 20555

Licensee Event Report 95-002, Docket 50-237 is being submitted as required by Technical Specification 6.6 and 10CFR50.73(a)(2)(ii).

This revised report is submitted to describe the results of the root cause investigation into the Local Leak Rate Test (LLRT) failure of Drywell Air Sample Valve 2-9205B.

Sincerely,

A handwritten signature in black ink, appearing to read "T. P. Joyce", is written over a horizontal line.

Thomas P. Joyce
Site Vice President

TPJ/MG:pt

Enclosure

cc: H. Miller, Regional Administrator, Region III
NRC Resident Inspector's Office
File/NRC
File/Numerical

250131

TPJ95\0081.95

9507250146 950721
PDR ADOCK 05000237
S PDR

Handwritten initials "LEZ" in a cursive style, with the number "11" written below them.