

Commonwealth Edison Company
Dresden Generating Station
6500 North Dresden Road
Morris, IL 60450
Tel 815-942-2920



July 24, 1995

TPJLTR 95-0086

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D. C. 20555

Licensee Event Report 95-009, Supplement 1, Docket 50-249 is being submitted as required by Technical Specification 6.6 and 10CFR50.73(a)(2)(i).

This supplement is being submitted to report the root cause and corrective actions taken for all test volumes that exceeded administrative local leakage limits during Dresden Unit 3 refuel outage number 13.

Sincerely,

A handwritten signature in black ink, appearing to read "T.P. Joyce", is written over a faint, larger version of the same signature.

Thomas P. Joyce
Site Vice President

TPJ/MG:pt

Enclosure

cc: H. Miller, Regional Administrator, Region III
NRC Resident Inspector's Office
File/NRC
File/Numerical

270011

TPJ95\0086.95

9507270176 950724
PDR ADQCK 05000249
S PDR

A Unicom Company

IF22
11