

Commonwealth Edison Company  
Dresden Generating Station  
6500 North Dresden Road  
Morris, IL 60450  
Tel 815-942-2920



September 15, 1995

TPJLTR 95-0112

U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D. C. 20555

Licensee Event Report 95-012, Rev. 01, Docket 50-249 is being submitted pursuant to 10CFR50.73(a)(2)(v)(C), any event or condition that alone could have prevented the fulfillment of the safety function of structures or systems that are needed to control the release of radioactive material, and 10CFR50.73(a)(2)(i)(B), any operation or condition prohibited by the plant's Technical Specification.

This LER revision is being issued to address an inadvertent omission in the original LER regrading previous secondary containment leak rate test failures and tests performed at wind speeds in excess of Technical Specification requirement.

Sincerely,

A handwritten signature in black ink, appearing to read "T.P. Joyce", is written over a horizontal line.

Thomas P. Joyce  
Site Vice President

TPJ/JW:pt

Enclosure

cc: H. Miller, Regional Administrator, Region III  
NRC Resident Inspector's Office  
File/NRC  
File/Numerical

TPJ95\0112.95

9509210265 950915  
PDR ADOCK 05000249  
S PDR

A Unicom Company

*JE22*