Commonwealth Edison pipany 1400 Opus Place Downers Grove, IL 60515



October 31, 1995

U. S. Nuclear Regulatory Commission Attn: Document Control Desk Washington, D.C. 20555

Subject: Dresden Nuclear Power Station Units 2 and 3 Quad Cities Nuclear Power Station Units 1 and 2 Transmittal of Quad Cities Design Documents for the Core Shroud Repair <u>NRC Docket Nos. 50-237/249 and 50-254/265</u>

Reference: P. Piet letter to U. S. NRC, dated October 2, 1995.

The purpose of this letter is to supplement the referenced submittal regarding design documentation for the core shroud repair at Dresden and Quad Cities Station. This is at the direct request of the NRC staff during a October 16, 1995 telecon. The attached report provides a complete summary on a station by station basis describing the impact and resolution of the seismic analysis discrepancy identified.

Additionally, the referenced submittal was inadvertently submitted only under the Dresden Station Docket. The information provided in the referenced submittal was intended for submittal under <u>both</u> Dresden and Quad Cities Station's Dockets. ComEd apologizes for any inconvenience this may have caused the NRC staff. If there are any further questions, please contact this office.

Sincerely,

Bob Rybak Nuclear Licensing Administrator

Attachment:

Evaluation of the Discrepancy in the RPV Internals Seismic Analysis, Dresden Units 2 and 3 and Quad Cities Units 1 and 2

cc: H. J. Miller, Regional Administrator - RIII
J.F. Stang, Project Manager - NRR
R. M. Pulsifer, Project Manager - NRR
C. G. Miller, Senior Resident Inspector - Quad Cities Office of Nuclear Facility Safety - IDNS

k:\nla\dresden\shroud\oct02\amend1.wpi 951103037 ADOCK PDR A Unicom Company.