

Commonwealth Edison Company
Dresden Generating Station
6500 North Dresden Road
Morris, IL 60450
Tel 815-942-2920



November 28, 1995

PGHLTR 95-0034

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D. C. 20555

Licensee Event Report 95-020, Docket 50-249 is being voluntarily submitted due to the fact that corrective actions which were stated in LER 94-18, Docket 0500237, were found not to have been fully implemented.

This transmittal contains the following commitments:

1. DAP 11-11 will be reviewed and revised as necessary to change wording of "present" setpoint to a term more indicative of a superseded setpoint. The change will minimize the potential of using a superseded design document. (Station Commitment Number (SCN) 249-180-95-02001)
2. Plant Engineering Personnel will be trained via tailgate meetings, to the revision to DAP 11-11. (SCN 249-180-95-02002)
3. The circumstances of the event and reasons for the error will be discussed in tailgate meetings with Work Analysts, along with the requirement to clearly and uniquely specify work requirements and the need to use correct design input in the preparation of work packages. (SCN 249-180-95-02003)

150048

L:\8307\8301\pghltr.95\0034.95

9512150153 951128
PDR ADOCK 05000249
S PDR

A Unicom Company

JEZ

4. **Electrical Maintenance Personnel will be trained via tailgate meetings to the circumstances of the event, the reasons for the error and the need to completely understand the work scope. (SCN 249-180-95-02004)**

Sincerely,



**Peter G. Holland
Regulatory Assurance Supervisor**

PGH/EJ:pt

Enclosure

**cc: H. Miller, Regional Administrator, Region III
NRC Resident Inspector's Office
File/NRC
File/Numerical**