Commonwealth Ediso Empany Dresden Generating Station 6500 North Dresden Road Morris, IL 60450 Tel 815-942-2920

March 22, 1996



JSP Ltr. #96-0042

U.S. Nuclear Regulatory Commission Document Control Desk Washington, D. C. 20555

Enclosed is Licensee Event Report 96-004, Docket 50-237 which is being submitted pursuant to 10CFR50.73(a)(2)(i)(b), which requires the reporting of any operation or condition prohibited by the plant's Technical Specifications.

This correspondence contains the following commitments:

- 1. DMP 200-03 will be revised to clearly identify guidance to the user when the Technical Specification limits of +/- 1% of the design setpoint was exceeded during valve setpoint testing (2371809600401).
- 2. A review of safety valve setpoint testing results from 1988 will be performed to identify if additional safety valve out of tolerance events have occurred and were not reported through the LER system. (2371809600402)
- 3. Operations will notify Quad Cities Nuclear Station, whose safety valves are tested at Dresden, making them aware of the missed reportability issue, for potential action at their site. (2371809600403)
- 4. A supplemental report will be provided to document the results of corrective action 2371809600402. (2371809600400S1)

Sincerely,

J. Stephen Perry Vice President BWR Operations

Enclosure

cc: H. Miller, Regional Administrator, Region III

NRC Resident Inspector's Office

File/NRC

File/Numerical

7603260101 760322 PDR ADDCK 05000237 S PDR IKDO!