

Commonwealth Edison Company
Dresden Generating Station
6500 North Dresden Road
Morris, IL 60450
Tel 815-942-2920

ComEd

June 13, 1996

50-237

JSPLTR. #96-0093

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D. C. 20555

The presentation made to Chairman Jackson in early May which supplied the April 30 goal results had an error in the Unit 2 High Pressure Systems Unavailability Ratio twelve month rolling average. The goal for this area was 0.017. A figure of 0.015 was presented. The correct value is 0.021. The remaining Safety System unavailability numbers were recalculated and verified and found to be correct as they were presented to Chairman Jackson.

The incorrect figure of 0.015 was the result of an error made by the individual performing the calculation. The planned unavailability of the Unit 2 High Pressure Coolant Injection system for June 1995 was inadvertently missed. This resulted in the change identified above. The error was discovered when the figure was calculated for May 1996.

Sincerely,



J. Stephen Perry
Site Vice President
Dresden Station

cc: H. Miller, Regional Administrator, Region III
NRC Resident Inspector's Office
Illinois Department of Nuclear Safety

200013

9606190315 960613
PDR ADOCK 05000237
PDR

A Unicom Company

A001
110