Commonwealth Edison Company Dresden Generating Sta 6500 North Dresden Road Morris, IL 60450 Tel 815-942-2920



February 14, 1997

JSPLTR: 97-0032

U. S. Nuclear Regulatory Commission Attn. Document Control Desk Washington, D. C. 20555

SUBJECT:

Dresden Station Unit 3

Retraction of Request for an Extension of the 18.5 Month

Operating Period Stipulated for Dresden Unit 3 Due to the Core

Shroud Cracking Issue. NRC Docket No. 50-249

REFERENCE:

(a) J. S. Perry (ComEd) letter to the USNRC Document Control Desk, dated September 12, 1997, "Extension of the 18.5 Month Operating Period Stipulated for Dresden Unit 3 Due to the Core Shroud Cracking Issue."

The purpose of this letter is to retract the request previously made for an extension to the 18.5 month operating period resulting from the Core Shroud cracking issue.

In the Reference (a) submittal, ComEd requested that the 18.5 month hot operating cycle be extended to 20.5 months to accommodate unplanned events that impacted the operating cycle.

Recently, it has been determined necessary to revise the start date of the Unit 3 Refuel Outage to start approximately one month earlier. As a result of the combination of the revised start and the recent forced outage, ComEd no longer needs the additional time in the operating cycle prior to the installation of the core shroud repair which is scheduled to take place during the next refueling outage (D3R14).

Accordingly, we withdraw the request for the extension to the 18.5 month operating period.



USNRC February 14, 1997

Please refer any questions you may have to Frank Spangenberg, Regulatory Assurance Manager, at 815-942-2920 x3800.

Sincerely,

Stephen Perry Site Vice President Dresden Station

cc: A. B. Beach, Regional Administrator - RIII

C. L. Vanderniet, Senior Resident Inspector - Dresden

C. G. Miller, Senior Resident Inspector - Quad Cities

J. F. Stang, Project Manager - NRR

R. M. Pulsifer, Project Manager - NRR Office of Nuclear Facility Safety - IDNS