

Commonwealth Edison Company
Dresden Generating Station
6500 North Dresden Road
Morris, IL 60450
Tel 815-942-2920



June 13, 1997

JSPLTR #97-0112

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555


Enclosed is Licensee Event Report 97-006, Docket 50-249, which is being submitted in accordance with 10CFR50.73(a)(2)(ii), which requires the reporting of any event or condition that resulted in the nuclear power plant being in a condition that was outside the design basis of the plant.

This correspondence contains the following commitment:

1. Dresden Station Engineering Department personnel involved with the Technical Review of Dresden Engineering Surveillance 8300-36 will be counseled by Engineering Management regarding their part in improperly identifying the "As Found" requirement during Service Test performance. (NTS #2491809700601)

If you have any questions, please contact Terry Riley, Dresden Regulatory Assurance Supervisor at (815) 942-2920 extension, 2714.

Sincerely,


J. Stephen Perry
Site Vice President
Dresden Station

1/1
7022

Enclosure

cc: A. Bill Beach, Regional Administrator, Region III
NRC Resident Inspector's Office

9706190282 970613
PDR ADOCK 05000249
S PDR



190025