Commonwealth Edison Company Dresden Generating Stat 6500 North Dresden Road Morris, IL 60450 Tel 815-942-2920



June 24, 1997

JSPLTR #97-0119

U.S. Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

Enclosed is Licensee Event Report 97-008, Docket 50-249, which is being submitted in accordance with 10CFR50.73(a)(2)(iv), which requires the reporting of any event or condition that resulted in manual or automatic actuation of any engineered safety feature (ESF), including the reactor protection system.

This correspondence contains the following commitments:

- 1) Establish a Peer Check Program within IMD. (237-180-97-01201)
- 2) Train all Instrument Maintenance Technicians in self-checking to include demonstration on a "STAR" simulator. (237-180-97-01204)

If you have any questions, please contact Terry Riley, Dresden Regulatory Assurance Supervisor at (815) 942-2920 extension, 2714.

Sincerely,

J Stephen Perry

Site Vice President

Dresden Station

Enclosure

cc: A. Bill Beach, Regional Administrator, Region III
NRC Resident Inspector's Office

2001

020036

