

Commonwealth Edison Company
Dresden Generating Station
6500 North Dresden Road
Morris, IL 60450
Tel 815-942-2920



October 3, 1997

JSPLTR #97-0171

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Enclosed is Licensee Event Report 97-009, Docket 50-249, which is being submitted in accordance with 10CFR50.73(a)(2)(v), which requires the reporting of any event or condition that alone could have prevented the fulfillment of the safety function of systems that are needed to mitigate the consequences of an accident.

The report contains the following commitment:

Enhance DIS 2300-15, High Pressure Coolant Injection System (HPCI) Gland Seal Condenser Level Control/Alarm Switch Functional Test, to physically inspect all four GSLO condenser hotwell level control and alarm switches. Inspection will include mercury bulb integrity. (NTS 249-180-97-00901)

If you have any questions, please contact Terry Riley, Dresden Regulatory Assurance Supervisor at (815) 942-2920 extension, 2714.

Sincerely,

J. Stephen Perry
Site Vice President
Dresden Station.

Enclosure

cc: A. Bill Beach, Regional Administrator, Region III
NRC Resident Inspector's Office

11
Ic22

010000

9710080251 971003
PDR ADOCK 05000249
S PDR

