



Corporate Office  
50 Founders Plaza, Suite 207  
East Hartford, CT 06108  
P: 860.569.0095  
www.cabreraseservices.com

June 26, 2017

Regional Administrator  
U.S. Nuclear Regulatory Commission  
Region I  
2100 Renaissance Boulevard, Suite 100  
King of Prussia, PA 19406-2713  
ATTN: Director, Division of Nuclear Materials Safety

Br. 3  
030353/6

RE: NRC Radioactive Materials License No. 06-30556-01, Amendment No. 08:  
Update to License Use in Areas of Exclusive Federal Jurisdiction at Site WR111, Hill Air Force  
Base, UT

Cabrera Services Inc. (Cabrera) is providing this written notification updating the status of  
temporary work activities at Hill Air Force Base (Site WR111). The following information is  
provided in accordance with License Condition No. 18B:

- **Temporary job site status:** Cabrera performed soils excavation and final status survey (FSS) gamma scans & soil sampling at Site WR111. Temporary job site controls were removed at the completion of remediation and after a review of gamma walkover survey results by Cabrera Health Physicists (HP). A locked chain-link fence remains in place pending review of off-site sample analytical results and transfer of the Site back to the Owner. Additional FSS may be conducted, if required to meet FSS data objectives. Otherwise, no other licensed activities are currently planned for the Site.
- **Disposition of any licensed radioactive material:** A total of 133 tons of radioactive material containing natural thorium were excavated and transported by dump truck to the US Ecology landfill in Grand View, Idaho for disposal.

An additional update or termination notice will be submitted when control of Site WR111 is returned to the Owner or additional soil remediation is scheduled based on FSS results. If you should have any questions, please contact me at (352) 610-2150.

Sincerely,

Michael S. Winters, CHP  
Radiation Safety Officer

600015

RADIOACTIVE MATERIALS-002



## ACKNOWLEDGEMENT - RECEIPT OF CORRESPONDENCE

## Name and Address of Applicant and/or Licensee

Cabrera Services, Inc.  
ATTN: Michael S. Winters, RSO, Corp. HP  
50 Founders Plaza  
Suite 207  
East Hartford, CT 06108

## Date

July 6, 2017

## License Number(s)

06-30556-01

## Mail Control Number(s)

600015

## Licensing and/or Technical Reviewer or Branch

Decommissioning & Technical Support Branch  
(Branch 3)

This is to acknowledge receipt of your: ☒ Letter and/or ☐ Application Dated: 06/26/2017

The initial processing, which included an administrative review, has been performed. ☒ *Notification*

☐ Amendment ☐ Termination ☐ New License ☐ Renewal

☒ There were no administrative omissions identified during our initial review.

☐ This is to acknowledge receipt of your application for renewal of the material(s) license identified above. Your application is deemed timely filed, and accordingly, the license will not expire until final action has been taken by this office.

☐ Your application for a new NRC license did not include your taxpayer identification number. Please complete and submit NRC Form 531, Request for Taxpayer Identification Number, located at the following link: <http://www.nrc.gov/reading-rm/doc-collections/forms/nrc531.pdf>  
Follow the instructions on the form for submission.

☐ The following administrative omissions have been identified:

Your application has been assigned the above listed MAIL CONTROL NUMBER. When calling to inquire about this action, please refer to this control number. Your application has been forwarded to a technical reviewer. Please note that the technical review, which is normally completed within 180 days for a renewal application (90 days for all other requests), may identify additional omissions or require additional information. If you have any questions concerning the processing of your application, our contact information is listed below:

Region I  
U. S. Nuclear Regulatory Commission  
Division of Nuclear Materials Safety  
2100 Renaissance Boulevard, Suite 100  
King of Prussia, PA 19406-2713  
(610) 337-5260, (610) 337-5313,  
(610) 337-5398, or (610) 337-5239