



Telegram

1973 APR 16 PH 6: 18

VEB246(191S)(1-032340C106)PD 04/16/73 1914

ICS IPNVEIA MVN

01287 TDVE MORRIS IL 112 04-16 535P CST

PMS MR BOYCE GRIER, DIRECTOR DIVISION OF COMPLIANCE

REGION THREE US ATOMIC ENERGY COMMISSION

799 ROOSEVELT RD GLEN ELLYN IL 60137

SUBJECT DP4-25

DRESDEN NUCLEAR POWER STATION UNIT THREE.

THIS WILL CONFIRM A CONVERSATION WITH MR MAURA OF YOUR OFFICE AT 1530 HOURS THIS DATE CONCERNING TWO SUSTAINED HIGH REACTOR PRESSURE SWITCHES BEING OUT OF CALIBRATION. THESE PRESSURE SWITCHES INIATE ISOLATION CONDENSOR AFTER A FIFTEEN SECOND TIME DELAY. ON 4-13-73 PS3-263-53B WAS FOUND TO TRIP AT 1075PSIG AND PS3-263-53D WAS FOUND TO TRIP AT 1073PSIG. TABLE 3.2.2 OF THE TECHINAL SPECIFICATION STATES THE TRIP LEVEL SETTING SHOULD BE LESS THAN OR EQUAL TO 1070PSIG.

SF-1201 (R5-69)

AFTER THE CALIBRATION SWITCH 53B TRIPPED AT 1052PSIG AND THE SWITCH 53D AT 1056PSIG.

W P WORDEN SUPERINTENDANT  
DRESDEN NUCLEAR POWER STATION  
COMMONWEALTH EDISON CO  
RRI  
MORRIS ILLINOIS

TELEGRAMS (OTHER THAN MONEY ORDERS),  
 Is SPECIAL DELIVERY requested? \_\_\_\_\_ (YES-AGENT, NO-ADDRESSEE)  
 ADDRESS SEE SECTION  
 N. r.  
 Date 4/17 Time did 8:50A To P.G. By EB  
 To be \_\_\_\_\_ or filed mc  
 Attempts to deliver (Indicate DA or BY)

SF-1201 (R5-69)