



Commonwealth Edison

One First National Plaza, Chicago, Illinois

Address Referred: Post Office Box 767
Chicago, Illinois 60690

September 19, 1975

Mr. Gaston Fiorelli, Chief
Reactor Operations Branch - Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Subject: Dresden Station Units 2 and 3
Response to Inspection Reports No.
50-237/75-21 and No. 50-249/75-18
NRC Docket Nos. 50-237 and 50-249

Dear Mr. Fiorelli:

Your letter, dated August 29, 1975, identified several areas of deviation from Edison standards. This letter is in response to those items.

Removal of foreign materials, inspection, and repair to fire stops began September 8, 1975.

Basic designs for all new fire stops and repair of all deficient fire stops call for the use of a ceramic fiber filler/thermal insulation covered with Flamemastic branch of fire retardant. Existing fire stops that are in accordance with Sargent and Lundy standards EA-175, EA-176, EA-177, EA-178, or EA-179 will not be modified. We estimate that this work should be completed in December, 1975. Any changes in design details necessitated by unforeseen field conditions will be incorporated in the final design documents.

The subject inspection reports have been reviewed for proprietary information and none was identified.

Very truly yours,

A handwritten signature in cursive script that reads 'R. L. Bolger'.

R. L. Bolger
Assistant Vice President