

Commonwealth Edison Company
Dresden Generating Station
6500 North Dresden Road
Morris, IL 60450
Tel 815-942-2920



May 12, 1998

JMHLTR: #98-0137

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D.C. 20555

Subject: Dresden Station Unit 2 Supplementary Response to NRC Generic Letter (GL) 96-01 "TESTING OF SAFETY-RELATED LOGIC CIRCUITS" NRC Docket Nos. 50-237

- Reference:
- (1) NRC Generic Letter 96-01, "TESTING OF SAFETY-RELATED LOGIC CIRCUITS" dated January 10, 1996
 - (2) J. Brons (ComEd) letter to U.S. NRC, dated April 19, 1996; ComEd Initial Response to GL 96-01.
 - (3) J. S. Perry (ComEd) letter to U.S. NRC, dated November 8, 1996 Supplemental Response to NRC Generic Letter (GL), GL 96-01,
 - (4) J. S. Perry (ComEd) letter to U.S. NRC, dated June 19, 1997 Supplemental Response to NRC Generic Letter (GL), GL 96-01,

The purpose of this letter is to report completion of the actions requested by reference (1) for Dresden Unit 2. Reference (2) provided the ComEd response to reference (1), and reference (3) amended the estimated completion dates for GL 96-01 based on revised dates for the unit refueling outages. Reference (4) provided closure for Dresden Unit 3.

The remaining Dresden 2 procedure reviews are now complete. Procedure changes have been completed and necessary surveillance testing was accomplished during the Dresden 2 D2R15 refueling outage which ended April 17, 1998.

9805210363 980512
PDR ADOCK 05000237
P PDR

100131


1/6
A067

USNRC
JMHLTR: #98-0137

May 12, 1998
Page 2

If you have any questions concerning this issue, please contact Mr. Frank A. Spangenberg, Dresden Station Regulatory Assurance Manager, at (815) 942-2920, ext. 3800.

Sincerely,


J. M. Heffley
Site Vice President
Dresden Station

cc: A. Bill Beach, Administrator USNRC Region III
L. W. Rossbach, Project Manager, NRR
K. Riemer, Senior Resident Inspector, Dresden Station
Office of Nuclear Facility Safety - IDNS